




WHEREVER TIRES ARE CHANGED™

# Pigtail Plug Safety Shims™



Lights won't flicker during travel. Lights stay on. ABS lights indicate properly. (ABS lights often come on with a poor plug connection). Drivers will be seen and protected. Installs in 5 minutes.



SAFETY SHIMS PN 92000



**EASY TO INSTALL** Our easy to use Pigtail Safety Shims firmly hold the plug in the receptacle ensuring tail lights stay on.



## SAVINGS

OUR SHIMS PREVENT PRONGS FROM WEARING, WHICH MAKE THE PLUGS/RECEPTACLES LAST MUCH LONGER

## SAFETY RATING

FEWER TICKETS AND INCIDENTS KEEP SAFETY RATINGS LOWER. THIS EQUATES TO LOWER INSURANCE PREMIUMS, MORE CONTRACTS AND MORE TOTAL REVENUES

## LOWER LIABILITY

LIGHTS STAY ON, BEING SEEN AND SAFE

## PROTECTION

LOWER ACCIDENT RISK, DRIVERS WILL BE SEEN AND PROTECTED.

Table with Savings:

Estimated Hard Costs	One Truck	20 Trucks	50 Trucks	100 Trucks
Replacement Cost of Plug / Receptacle	\$75.00	\$1,500.00	\$3,750.00	\$7,500.00
Shop Time Labor	\$70.00	\$1,400.00	\$3,500.00	\$7,000.00
Downtime Loss of Miles	\$105.00	\$2,100.00	\$5,250.00	\$10,500.00
Driver Loss of Pay	\$15.75	\$315.00	\$787.50	\$1,575.00
Estimated Loss Potential	\$265.75	\$5,315.00	\$13,287.50	\$26,575.00
Pigtail Plug Safety Shim (pair)	\$14.95	\$299.00	\$747.50	\$1,495.00
<b>TOTAL SAVINGS</b>	<b>\$248.80</b>	<b>\$4,976.00</b>	<b>\$12,440.00</b>	<b>\$24,880.00</b>

www.KENTOOL.com

1-888-536-8665

768 E. North Street, P.O. Box 9320 | Akron, Ohio 44305 | Fax: 800-872-4929 | Phone: 330-535-7177 | Fax: 330-535-1345 | E-mail: sales@kentool.com

© 2021 Ken-Tool. All Rights Reserved. KT08102021