



# Zip's Truck Equipment

316 W. Milwaukee Street  
New Hampton, Iowa 50659  
Phone: 641-394-3166  
Fax: 641-394-4044



## FIELD iD

### Visual Inspection

Page: 1 of 7

**Customer:** \_\_\_\_\_  
**Address:** \_\_\_\_\_  
**Serial No:** J12073  
**Equipment Type:** Car Carrier  
**Event Performed:** Car Carrier Inspection  
**Result:** Pass  
**Inspected By:** \_\_\_\_\_

**Division:** null  
**Location:** \_\_\_\_\_  
**Phone:** \_\_\_\_\_  
**Reference #:** 1HTMMAAM33H568121  
**Order #:** \_\_\_\_\_  
**Inspected On:** 07/22/15 2:46 PM CDT  
**Total Score:** \_\_\_\_\_  
**Comments:** \_\_\_\_\_

Michigan Shop Service Tech 1

| Car Carrier-J12073               |                        |                                     |  |
|----------------------------------|------------------------|-------------------------------------|--|
| * Year:                          | <u>2003</u>            | Work Lights In Lightbar:            | <u>Yes</u>                                   |
| * Make:                          | <u>International</u>   | * Side Puller Make:                 | <u>No</u>                                    |
| * Model:                         | <u>4300</u>            | PTO Type:                           | <u>Hot Shift</u>                             |
| * Engine Model:                  | <u>DT466</u>           | Switch Panel & # Of Switches:       | <u>In Dash - 6</u>                           |
| * Fuel Type:                     | <u>Diesel</u>          | In Cab Throttle:                    | <u>Yes</u>                                   |
| * Transmission Type:             | <u>Automatic</u>       | * Bed/Side Puller/Pylon Color ONLY: | <u>Blue</u>                                  |
| * Transmission Brand:            | <u>Allison</u>         | * Brake Type:                       | <u>Hydraulic</u>                             |
| * Odometer Reading:              | <u>240351</u>          | * Suspension Type:                  | <u>Air Ride</u>                              |
| Hour Meter Reading:              | <u>12474</u>           | * Air Compressor-FOR Brake System:  | <u>Yes</u>                                   |
| Rear Vision Camera System/Brand: | <u>No</u>              | Engine Brake:                       | <u>No</u>                                    |
| Remote Keyless Entry:            | <u>No</u>              | Air Dryer:                          | <u>No</u>                                    |
| * Cab to Axle:                   | <u>144"</u>            | * Air Conditioning:                 | <u>Yes</u>                                   |
| * Wheel-Base:                    | <u>210"</u>            | * Radio:                            | <u>AM/FM/CD</u>                              |
| Wheel Type:                      | <u>Steel/ 1/2 sims</u> | Navigation System/Brand:            | <u>No</u>                                    |
| * Cab Color ONLY:                | <u>Blue</u>            | * Driver Seat:                      | <u>Vinyl Air Ride High Back w/Rt Armrest</u> |
| * Body Make:                     | <u>Vulcan</u>          | Passenger Seat:                     | <u>Vinyl 2 Man High Back</u>                 |
| * Body Length:                   | <u>21'</u>             | Windows:                            | <u>Power</u>                                 |
| * Body Model:                    | <u>Steel</u>           | Door Locks:                         | <u>Power</u>                                 |
| * Body Serial Number:            | <u>VS21-3582-002W</u>  | Window Deflectors:                  | <u>No</u>                                    |
| Body Width:                      | <u>96"</u>             | Rear Sliding Window:                | <u>No</u>                                    |
| * Beacon/Lightbar Make:          | <u>Federal Signal</u>  | Cruise Control:                     | <u>Yes</u>                                   |
| * Beacon/Lightbar Model:         | <u>JetStream</u>       | Tilt Steering Wheel:                | <u>Yes</u>                                   |
| Directional Lightbar/Brand:      | <u>No</u>              | Air Horn:                           | <u>Yes</u>                                   |
|                                  |                        | Flooring:                           | <u>Rubber or Vinyl</u>                       |

Owner: \_\_\_\_\_

Location: \_\_\_\_\_

|                            |                         |                                  |                                    |
|----------------------------|-------------------------|----------------------------------|------------------------------------|
| Floor Mats:                | No                      | Extra Lights on BED/Where:       | Yes - Sides of Pylon And Bed Sides |
| Bug Shield:                | No                      | Crossmembers (Steel beds only):  | 8" Spacing                         |
| Sunvisor:                  | No                      | Bed Mounted D-Rings & #:         | NA                                 |
| * Bumper:                  | Chrome                  | Stake Pockets & #:               | NA                                 |
| Grille:                    | Chrome                  | Key Slots & #:                   | Yes 4 Key Slots                    |
| Front Tow Hooks:           | No                      | Bed Floor Type:                  | Steel                              |
| Engine Block Heater:       | Yes                     | Toolbox System/Where:            | 2-48" Aluminum - R&L Sides         |
| Extra Lights on CAB/Where: | Yes - In Grille         | Open Top Storage & Size:         | No                                 |
| Jumper Cable Plug/Where:   | No                      | Dri-Dek In Toolboxes:            | No                                 |
| Jumper Cable:              | No                      | Air Hose Reel/Mounted Where:     | No                                 |
| Mirrors:                   | Power/Lighted Swing Out | Auxiliary Air Compressor:        | No                                 |
| Additional Mirrors:        | Convex Mirrors          | Snatch Blocks:                   | Yes 1                              |
| Spot Light:                | None                    | V-Chain/V-Strap Assemblies:      | No                                 |
| Fuel Tank/Where:           | 2 Steel - R&L Sides     | J-Chains & #:                    | No                                 |
| Fuel Tank Gallons:         | 55 Each                 | Straps/Rachets:                  | No                                 |
| Vertical Exhaust Stack:    | No                      | Fire Extinguisher:               | No                                 |
| Cab Roof Marker Lights:    | Yes                     | Warning Triangle Kit:            | No                                 |
| Tread Type Rear:           | Mud & Snow              | Tow Light System:                | No                                 |
| * Tire Size-Front:         | 245/70R19.5             | Dual Controls:                   | Yes                                |
| Tire Depth-Front:          | 9/32 miss matched       | Front/Rear Safety Chains:        | Yes Both                           |
| * Tire Size-Rear Axle:     | 245/70R19.5             | Light Plug Ins:                  | Yes CR6                            |
| Tire Depth-Rear Axle:      | 7/32 miss matched       | Hook Up Lights:                  | Yes                                |
| Top Hat Kit:               | No                      | * Wheel Lift/Wheel Lift Arms:    | Yes with L-Scoops                  |
| Lug Nut Covers:            | No                      | Wheel Lift Style:                | Vulcan Strapless Scoops            |
| Sub-Frame Finish:          | Painted                 | Live Air Hook Up/Where:          | Yes - LH Side Next To Battery Box  |
| Dump Angle:                | Normal                  | Gas Cans/holders/Where:          | No                                 |
| Dock Stabilizer:           | No                      | Trash Cans/holders/Where:        | No                                 |
| Side Rails:                | Steel Tube Fixed        | Self Loading Dollies:            | No                                 |
| Rub-Rails:                 | No                      | Go-Jaks:                         | No                                 |
| # of Winches:              | 1                       | Trailer Hitch:                   | Built-In                           |
| Winch Brand:               | Ramsey                  | Special Equipment Storage/Where: | No                                 |
| Winch Capacity:            | 8,000# Worm Type        |                                  |                                    |
| Winch Clutch Release:      | Yes Mechanical          |                                  |                                    |
| Winch Work Lights:         | Yes                     |                                  |                                    |
| Cable Tensioner:           | Yes                     |                                  |                                    |
| Cable Roller Guide:        | Yes                     |                                  |                                    |
| Remote Control:            | No                      |                                  |                                    |
| Pylon/Cab Guard:           | Stationary Steel        |                                  |                                    |
| Work Lights:               | No                      |                                  |                                    |
| Stop/Turn/Tail On Pylon:   | Yes                     |                                  |                                    |

| Inspector Name       | Status                   | Comments |
|----------------------|--------------------------|----------|
| Enter name here      | Mark. Dave               |          |
| Engine Check         | Status                   | Comments |
| Ability to Start     | Starts Normally          |          |
| Engine Blow-By Check | Has some Blow-By         |          |
| Engine Oil Leaks     | No Oil Leaks Observed    |          |
| Engine Noise         | Engine sounds are normal |          |

Owner: \_\_\_\_\_

Location: \_\_\_\_\_

| Engine Check                          | Status   | Comments |
|---------------------------------------|--|----------|
| Engine Warning Lights                 | No Check<br>Engine Lights<br>are on                                  |          |
| Engine Water Leaks                    | No Water<br>Leaks  |          |
| Performance                           | Performs<br>Normally   |          |
| Engine Mounts                         | In Good<br>Condition   |          |
| Other Engine Notes                    |  |          |
| Engine Brake                          |  |          |
| Batteries                             | Status   | Comments |
| Condition of Cables                   | Corroded Need<br>Cleaning  |          |
| Condition of<br>Batteries             | Do Not Hold<br>Charge Due to<br>Battery                              |          |
| Load Test                             | Fail   |          |
| Cooling System                        | Status   | Comments |
| Radiator                              | In Good<br>Condition   |          |
| Fan                                   | In Good<br>Condition   |          |
| Fan Clutch                            | In Good<br>Condition   |          |
| Fan Shroud                            | In Good<br>Condition   |          |
| Water Hoses                           | In Good<br>Condition   |          |
| Fan Belt                              | In Good<br>Condition.<br>Needs a/c<br>belt                           |          |
| Other Cooling<br>Condition Notes      |  |          |
| Automatic<br>Transmission Check       | Status   | Comments |
| Transmission<br>Operation             |  |          |
| Other Transmission<br>Notes           |  |          |
| Manual<br>Transmission Check          | Status   | Comments |
| Shifting                              |  |          |
| Clutch Operation                      |  |          |
| Throw-Out Bearing                     |  |          |
| Transmission Noise                    |  |          |
| Other Transmission<br>Notes           |  |          |
| Overall Body<br>Condition             | Status   | Comments |
| Overall Condition                     | Fair   |          |
| Other Overall Body<br>Condition notes |  |          |
| Cab Exterior                          | Status   | Comments |
| Hood                                  | Dented or<br>Cracked   |          |
| Right Fender                          | Dented or<br>Cracked   |          |
| Left Fender                           | Scratched  |          |
| Grille                                | In Good<br>Condition   |          |
| Back of Cab                           | Good<br>Condition  |          |
| Driver Side Door                      | Rusted   |          |
| Passenger Side Door                   | Dented   |          |
| Roof                                  | Good<br>Condition  |          |
| Other Cab Exterior<br>Notes           |  |          |
| Fuel Tank Appearance                  | Rusty and in<br>Need of Paint  |          |
| Entry Steps                           | In Need of<br>Paint  |          |
| Head-Light Doors                      | Cracked/Broke<br>n or Missing.<br>Passengers<br>side mounts<br>broke |          |
| Battery Box                           | In Good<br>Condition   |          |
| Driver Side Door<br>Hinges            | Worn -<br>Useable  |          |

| Cab Exterior                      | Status  | Comments |
|-----------------------------------|---|----------|
| Passenger Side Door<br>Hinges     | In Good<br>Condition                                |          |
| Front Bumper                      | Status  | Comments |
| Factory Front Bumper              | Dented/<br>Scratched or<br>Rusted                   |          |
| Front Push Bumper                 |   |          |
| Glass Condition                   | Status  | Comments |
| Windshield                        | Stone chips<br>and wiper<br>marks                   |          |
| Driver Side Window                | Good<br>Condition                                   |          |
| Passenger Side Windw              | Good<br>Condition                                   |          |
| Back Window                       | Good<br>Condition                                   |          |
| Other Glass Condition<br>Notes    |   |          |
| Overall Interior<br>Condition     | Status  | Comments |
| Overall Condition                 | Fair  |          |
| Other Overall<br>Interior Notes   |   |          |
| Interior Condition                | Status  | Comments |
| Drivers Seat                      | Needs Repair  |          |
| Passenger Seat                    | Needs Repair  |          |
| Rear Seat                         |   |          |
| Floor Mat                         |   |          |
| Instrument Cluster                | Fair  |          |
| Dash                              | In Good<br>Condition                                |          |
| Door Panels                       | In Good<br>Condition                                |          |
| Electric Door Locks               | Fair<br>Condition                                   |          |
| Other Interior<br>Condition Notes |   |          |
| Electric Windows                  | Operate<br>Properly                                 |          |
| Door Handles                      | In Good<br>Condition                                |          |
| Air Vents                         | In Good<br>Condition                                |          |
| Headliner                         | In Good<br>Condition<br>The visors<br>need some att |          |
| Other Interior Notes              |   |          |
| Door Seals                        | In Good<br>Condition                                |          |
| Floor Mats                        |   |          |
| Seat Belts                        | In Operative  |          |
| Windshield Wipers                 | Status  | Comments |
| Wiper Arms                        | In Need of<br>Repair                                |          |
| Wiper Blades                      | In Need of<br>Repair                                |          |
| Washer Tank                       | In Good<br>Condition                                |          |
| Washer Control Switch             | In Good<br>Condition                                |          |
| Heating                           | Status  | Comments |
| Heater Controls                   | Inoperative   |          |
| Fan Motor                         | Excellent<br>Condition                              |          |
| Heater                            | Heats<br>Appropriately                              |          |
| Other Heat Notes                  | Heater switch<br>is wired with<br>toggle switch     |          |
| Air Conditioning                  | Status  | Comments |
| Overall Condition                 | System Is<br>Open                                   |          |
| Air Conditioning<br>Controls      | In Good<br>Condition                                |          |
| Electrical System-<br>Chassis     | Status  | Comments |
| Interior lights                   | All Interior<br>Light Operate                       |          |
| Turn Signals                      | Some Lights<br>Inoperative                          |          |

Owner: \_\_\_\_\_

Location: \_\_\_\_\_

| Electrical System-Chassis      | Status   | Comments        |
|--------------------------------|--|-----------------|
| Head Lights                    | Operate Normally                               |                 |
| Alternator                     | Performs Normally                              |                 |
| Guages                         | All Gauges Perform Properly                    |                 |
| Dash Lights                    | Dash Lights Perform Normally                   |                 |
| Cab Marker Lights              | Marker Lights Perform Normally                 |                 |
| Back-Up Lights                 | Bank-Up Lights Inoperative                     |                 |
| Back-Up Alarm                  | Doesn't Operate                                |                 |
| 4-Way Flashers                 | Doesn't Operate                                |                 |
| Windshield Wipers              | Perform Normally                               |                 |
| Other Electrical System Notes  |  |                 |
| Cruise Control                 | N/A  |                 |
| Engine Throttle                | Operates Normally (Note Type)                  |                 |
| <b>Drive-Line</b>              | <b>Status</b>                                  | <b>Comments</b> |
| U-Joints                       | In Good Condition                              |                 |
| Rear Differential              | In good condition                              |                 |
| Transfer Case                  |  |                 |
| Other Drive-Line Notes         |  |                 |
| Hanger Bearings                | In Good Condition                              |                 |
| <b>Brakes</b>                  | <b>Status</b>                                  | <b>Comments</b> |
| Air Compressor                 |  |                 |
| System Air Leaks               |  |                 |
| Air Dryer                      |  |                 |
| Applied Brakes                 |  |                 |
| Brake Adjusters                |  |                 |
| Air Lines                      | Leaking  |                 |
| Low Air Pressure Warning       |  |                 |
| Front Brake Drums              |  |                 |
| Front Drive Axle Brake Drums   |  |                 |
| Front Brake Calipers           | In Good Condition                              |                 |
| Front Brake Linings            | Under 50%. Need repl. ced                      |                 |
| Pusher Axle Brake Drums        |  |                 |
| Pusher Axle Brake Linings      |  |                 |
| Front Drive Axle Brake Linings |  |                 |
| Rear Drive Axle Brake Drums    |  |                 |
| Rear Brake Calipers            | In Good Condition                              |                 |
| Rear Drive Axle Brake Linings  | 60 or Better                                   |                 |
| Emergency Brake                |  |                 |
| ABS Light                      | Showing Problem (ON)                           |                 |
| Brake Pedal Pads               |  |                 |
| Other Brake Notes              |  |                 |
| <b>Shock Absorbers</b>         | <b>Status</b>                                  | <b>Comments</b> |
| Front Shocks                   | Needs Replacement                              |                 |
| Rear Front Shocks              | Needs Replacement Missing mount on driver side |                 |
| <b>Wheels</b>                  | <b>Status</b>                                  | <b>Comments</b> |
| Front Axle Rims/Wheels         | Wheel In Good Condition                        |                 |

| Wheels                                  | Status  | Comments        |
|---|---|-----------------|
| Pusher Axle Rims/Wheels                 |   |                 |
| Front Drive Axle Rims/Wheels            |   |                 |
| Front Drive Axle Nuts and Studs (2) (2) |   |                 |
| Rear Drive Axle Rims/Wheels             |   |                 |
| Fronts Axle Nut and Studs               | In Good Condition                             |                 |
| Pusher Axle Nut and Studs               |   |                 |
| Rear Drive Axle Nuts and Studs          | In Good Condition                             |                 |
| Wheel Simulators Front Axle             | Damaged. Missing left side                    |                 |
| Wheel Simulators Pusher Axle            |   |                 |
| Wheel Simulators Front Drive Axle       |   |                 |
| Wheel Simulators Rear Drive Axle        | Missing                                       |                 |
| Aluminum Wheels Front Axle              |   |                 |
| Aluminum Wheels Pusher Axle             |   |                 |
| Aluminum Wheels Front Drive Axle        |   |                 |
| Aluminum Wheels Rear Drive Axle         |   |                 |
| <b>Wheel Hubs</b>                       | <b>Status</b>                                 | <b>Comments</b> |
| Front Wheel Seals                       | In Good Condition                             |                 |
| Pusher Axle Wheel Seals                 |   |                 |
| Front Drive Axle Wheel Seals            |   |                 |
| Rear Drive Axle Wheel Seals             | In Good Condition                             |                 |
| Oil Filled Hubs Front Axle              |   |                 |
| Oil Filled Hubs Pusher Axle             |   |                 |
| Oil Filled Hubs Front Drive Axle        |   |                 |
| Oil Filled Hubs Rear Drive Axle         |   |                 |
| Front Wheel Bearings                    | Not Adjusted but No Issue Visible             |                 |
| Front Drive Axle Wheel Bearings         |   |                 |
| Pusher Axle Wheel Bearings              |   |                 |
| Rear Drive Axle Wheel Bearings          | Not Adjusted but No Issue Visible             |                 |
| <b>Tires</b>                            | <b>Status</b>                                 | <b>Comments</b> |
| Front Axle                              | Replaced With New                             |                 |
| Pusher Axle                             |   |                 |
| Front Drive Axle                        |   |                 |
| Rear Drive Axle                         | Replaced With New                             |                 |
| Notes on Tires                          |   |                 |
| <b>Exhaust System</b>                   | <b>Status</b>                                 | <b>Comments</b> |
| Manifold                                | In Good Conditon                              |                 |
| Exhaust Tubing                          |   |                 |
| Muffler                                 |   |                 |
| DPF System                              |   |                 |
| Emnsions Warning Light                  |   |                 |
| Exhaust Shield                          |   |                 |
| Exhaust Stack                           |   |                 |
| Exhaust Mounting Bracket                |   |                 |
| <b>Frame</b>                            | <b>Status</b>                                 | <b>Comments</b> |
| Integrity of Frame                      | Swelling Between Frame & Liner - Not Critical |                 |
| <b>Suspension</b>                       | <b>Status</b>                                 | <b>Comments</b> |

Owner: \_\_\_\_\_

Location: \_\_\_\_\_

| Suspension                   | Status  | Comments |
|------------------------------|---|----------|
| Air Bags                     |   |          |
| Air Leaks                    |   |          |
| Air Lines                    |   |          |
| Spring Packs                 | In Good Condition                             |          |
| Front Spring Hangars         | In Good Condition                             |          |
| Rear Spring Hangars          | In Good Condition                             |          |
| Radius Arms                  | In Good Condition                             |          |
| Rear Suspension Bushings     | In Good Condition                             |          |
| Air Leveling Valve           | Needs Replacement or Repair                   |          |
| Steering and Front Axle      | Status  | Comments |
| Steering Pump                | Operates Normally                             |          |
| Steering Lines               | In Good Operating Condition                   |          |
| Steering Sector              | In Good Operating Condition                   |          |
| King Pins/Ball Joints        | In Good Condition                             |          |
| Steering Shaft               | In Good Condition                             |          |
| Pitman Arm                   | Loose on Output Shaft Needs replaced          |          |
| Drag Link                    |   |          |
| Tie Rod                      | In Good Condition                             |          |
| Toe in Check                 |   |          |
| 4x4 Hubs                     |   |          |
| Steering Wheel               | Steering Wheel in Good Cosmetic Condition     |          |
| Steering Wheel Position      | Steering Wheel In Correct Postion When Driven |          |
| Fuel System                  | Status  | Comments |
| Fuel Gauge                   |   |          |
| Fuel Tank                    | Dented. Looks bad                             |          |
| Fuel Fill                    | Fills Normally                                |          |
| Fuel Lines                   | In Good Condition                             |          |
| Fuel Filter                  | Not Replaced                                  |          |
| Glow Plugs or Exhaust Heater | Status  | Comments |
| Glow Plug Operation          | Glow Perform Normally                         |          |
| Intake Manifold Heater       |   |          |
| Fluids                       | Status  | Comments |
| Windshield Washer            | Not Checked                                   |          |
| Engine Oil                   | Appears That It Needs to be Changed           |          |
| Radiator Anti-Freeze         | Full  |          |
| Transmission Fluid           | Full  |          |
| Transfer Case Oil            |   |          |
| Front Drive Axle             |   |          |
| Rear Drive Axle              |   |          |
| Battery Acid Levels          |   |          |
| Hydraulic Oil                | Low Level                                     |          |
| Brake Fluid                  | At Proper Level                               |          |
| Power Steering Fluid         | Low   |          |
| Winch 1 Oil                  | Not Checked                                   |          |
| Winch 2 Oil                  |   |          |
| Winch 3 (Above Cab) Oil      |   |          |

| Filters                        | Status                                  | Comments |
|--------------------------------|---|----------|
| Water Filter                   |   |          |
| Engine Oil Filter              | Original (Not replaced)                 |          |
| Transmission Oil Filter        | Original (Not replaced)                 |          |
| Fuel Filter                    | Original (Not replaced)                 |          |
| Carrier Hydraulic System       | Not Changed                             |          |
| Engine Air Filter              | Inspected in Good Condition             |          |
| Chassis Lubrication Points     | Status                                  | Comments |
| King Pins/Ball Joints          | Appears To have Been Well Greased       |          |
| Tie-Rods Ends                  | Appears Dry                             |          |
| Steering Shaft Bearing         | Appears Dry                             |          |
| Drag Link                      | Appears Dry                             |          |
| Clutch Linkage                 |   |          |
| Throw-Out Bearing              |   |          |
| Drive-Line U-Joints            | Appears To have Been Well Greased       |          |
| S-Cam Shafts                   |   |          |
| Slack Adjusters                |   |          |
| Spring Hangars                 |   |          |
| Door Locks and Hinges          | In Need of Lubrication                  |          |
| Overall Car Carrier Condition  | Status                                  | Comments |
| Overall Condition              | Fair                                    |          |
| Carrier Deck                   | Status                                  | Comments |
| Aluminum Deck Condition        |   |          |
| Steel Deck Condition           |   |          |
| Aluminum Deck Side-rails       |   |          |
| Steel Deck Side-rails          |   |          |
| Steel Deck Side-rails Paint    |   |          |
| Aluminum Tail Section          |   |          |
| Rear Rollers                   |   |          |
| Re-movable Side Rails Steel    |   |          |
| Re-movable Side Rails Aluminum |   |          |
| Anti-Tilt Protection System    | In Need of Repair                       |          |
| Power Take-Off                 | Status                                  | Comments |
| Operation                      | Operates Normally                       |          |
| Oil Leaks                      | No Oil Leaks                            |          |
| PTO Warning Light              | In Good Operating Condition             |          |
| Shifting Mechanism             |   |          |
| Air Leaks                      |   |          |
| Hydraulic Pump                 | Status                                  | Comments |
| Oil Leaks                      | No Oil Leaks                            |          |
| Operation                      | Pump Operates Normally                  |          |
| Pump Pressure                  |   |          |
| Pump Flow                      |   |          |
| Control Valve                  | Status                                  | Comments |
| Oil Leaks                      | Leaks From Valve Section                |          |
| Operation                      | Operates Normally                       |          |
| Control Levers and Rods        | Loose and Worn Pins and Rod Connections |          |
| Control Box                    | Bent or Damaged                         |          |
| Knobs                          | In Good Condition                       |          |

Owner: \_\_\_\_\_

Location: \_\_\_\_\_

| Control Valve                           | Status                            | Comments |
|---|-----------------------------------|----------|
| Control Decals                          | Missing or in Need of Replacement |          |
| Hydraulic System Hoses                  | Status                            | Comments |
| Oil Leaks                               | In Operating Condition            |          |
| Hydraulic System Leaks                  | Status                            | Comments |
| Winch Hoses                             | No Oil Leaks                      |          |
| Lift Cylinder Hoses                     | Leaks Between Cylinders and Valve |          |
| Extension Cylinder Hoses                | No Oil Leaks                      |          |
| Wheel-Lift Tilt Cylinder Hoses          | No Oil Leaks                      |          |
| Wheel-Lift Extend Cylinder Hoses (2)    | No Oil Leaks                      |          |
| Hydraulic Pump Hoses                    | No Oil Leaks                      |          |
| Hydraulic Filter                        | No Oil Leaks                      |          |
| Bed Lift Cylinders                      | Oil Leaking                       |          |
| Extend Cylinder                         | No Oil Leaks                      |          |
| Wheel-Lift Tilt Cylinder                | No Oil Leaks                      |          |
| Wheel-Lift Extend Cylinder              | No Oil Leaks                      |          |
| Wheel-Lift Claw Cylinder Drivers Side   |                                   |          |
| Wheel-Lift Claw Cylinder Passenger Side |                                   |          |
| Pylon                                   | Status                            | Comments |
| Overall Condition                       | In Good Condition                 |          |
| Winch                                   | Status                            | Comments |
| Oil Leaks                               | No Oil Leaks                      |          |
| Free-Wheel Mechanism Winch 1            | Operates Normally                 |          |
| Free-Wheel Mechanism Winch 2            |                                   |          |
| Free-Wheel Mechanism Winch 3            |                                   |          |
| Housing Winch 1                         | In Good Condition                 |          |
| Housing Winch 2                         |                                   |          |
| Housing Winch 3                         |                                   |          |
| Operation Without Load                  |                                   |          |
| Operation Without Load Notes            |                                   |          |
| Test Operation Loaded                   |                                   |          |
| Test Operation Notes                    |                                   |          |
| Winch 1 Cable                           | Replaced With New                 |          |
| Winch 2 Cable                           |                                   |          |
| Winch 3 Cable                           |                                   |          |
| Cable Tensioner                         | In Good Condition                 |          |
| Wheel-Lift                              | Status                            | Comments |
| L-Arms/Scoops                           | In Good Condition                 |          |
| L-Arm Straps                            | Missing                           |          |
| L-Arm Storage                           | In Good Condition                 |          |
| Driver Side Claw                        |                                   |          |
| Passenger Side Claw                     |                                   |          |
| Driver Side Slide Tray                  | In Good Condition                 |          |
| Passenger Side Slide Tray               | In Good Condition                 |          |
| Passenger Side Slide Tray Locks         | In Good Condition                 |          |
| Driver Side Slide Tray Locks (2)        | In Good Condition                 |          |
| Driver Side Front Stops (Vulcan)        |                                   |          |
| Passenger Side Front Stops (Vulcan)     |                                   |          |
| Driver Side L-Arm Swivel                | In Good Condition                 |          |
| Passenger Side L-Arm Swivel (2)         | In Good Condition                 |          |

| Wheel-Lift                            | Status                            | Comments |
|---------------------------------------|-----------------------------------|----------|
| Center Pivot Pin and Bushing          | In Good Condition                 |          |
| Wheel-Lift Cross-Bar                  | In Good Condition                 |          |
| Pins and Bushings                     | In Fair Condition                 |          |
| Extension Tube                        | In Good Condition                 |          |
| Outer Wheel-Lift Assembly             | In Good Condition                 |          |
| Wheel-Lift Swivel Lock Pins           | Missing                           |          |
| Wheel-Lift Swivel Lock Pins (2)       | Missing                           |          |
| Scoop Locking Pins and Chains         | In Good Condition                 |          |
| Driver Side Claw Cylinders            |                                   |          |
| Wear Pads                             | Missing or In Need of Replacement |          |
| Carrier Electrical Systems            | Status                            | Comments |
| Switch Panel                          | In Good Condition                 |          |
| Overall Wiring Condition              | Exposed or Patched Wiring         |          |
| Bed Wiring Harness Condition          | Exposed or Patched Wiring         |          |
| Junction Boxes Condition              | In Good Condition                 |          |
| Marker Lights                         | In Good Condition                 |          |
| Driver Side Turn Signals Upper        | Inoperative                       |          |
| Passenger Side Turn Signals Upper     | Inoperative                       |          |
| Driver Side Turn Signals Upper Lower  | Inoperative                       |          |
| Passenger Side Turn Signals Lower     | Inoperative                       |          |
| Extra Warning Lights                  |                                   |          |
| Extra Clearance Lights                |                                   |          |
| Upper Work Lights                     | In Good Condition                 |          |
| Lower Work Lights                     | In Good Condition                 |          |
| Work Lights Mounted Near Winch        | In Good Condition                 |          |
| Beacon Light                          | In Good Condition                 |          |
| Tow Light Plug at Tail-Board          | In Good Condition                 |          |
| License Plate Light                   | Lights Missing                    |          |
| Tool Boxes                            | Status                            | Comments |
| Box Driver Side 1                     | In Good Condition                 |          |
| Box Driver Side 2                     | Door Broken or Missing            |          |
| Box Passenger Side 1                  |                                   |          |
| Box Passenger Side 2                  |                                   |          |
| Fenders                               | Status                            | Comments |
| Drivers Side                          | In Good Condition                 |          |
| Passenger Side                        | Bent or Damaged                   |          |
| Carrier Components                    | Status                            | Comments |
| Bed Hold-Downs                        | In Good Condition                 |          |
| Rear Bed Mounting (Pivot Pin)         | In Good Condition                 |          |
| Driver Side Tail-Light Housing        | Rusty But Usable                  |          |
| Passenger Side Tail-Light Housing (2) | Rusty But Usable                  |          |
| Rear Tail Section                     | Rusty - In Need of Paint          |          |
| Body Lubrication Points               | Status                            | Comments |
| Bed Pivot Pin                         | Appears Dry                       |          |

Owner: \_\_\_\_\_

Location: \_\_\_\_\_

| Body Lubrication Points        | Status                                   | Comments |
|--------------------------------|--|----------|
| Lift Cylinder Pins             | Appears to Have Been Regularly Serviced  |          |
| Wheel-lift Tilt Pin            | Appears to Have Been Regularly Serviced  |          |
| Wheel-Lift Pivot Pin           | Appears to Have Been Regularly Serviced  |          |
| Wheel-Lift Upper Slide Pads    | Appears Dry                              |          |
| Wheel-Lift Lower Slide Pads    | Appears Dry                              |          |
| Deck Slide Back Wear Pads      | Appears to Have Been Regularly Serviced  |          |
| Tool Box Door Hinges and Locks | In Need of Lube                          |          |
| Carrier Chains                 | Status                                   | Comments |
| Front Safety Chains            | In Good Condition                        |          |
| Rear Safety Chains             | In Good Condition but Missing Lock Clips |          |
| V-Chains Chains                | Missing                                  |          |
| V-Chains Straps                | Missing                                  |          |
| Mud-Flaps                      | Status                                   | Comments |
| Mounting Brackets              | In Good Condition                        |          |
| Mud-Flap                       | In Good Condition                        |          |