



Zip's Truck Equipment

316 W. Milwaukee Street
New Hampton, Iowa 50659
Phone: 641-394-3166
Fax: 641-394-4044



FIELD iD

Visual Inspection

Page: 1 of 7

Customer: _____

Address: _____

Serial No: J13768

Equipment Type: Car Carrier

Event Performed: Car Carrier Inspection

Result: Pass

Inspected By: _____

Division: null

Location: _____

Phone: _____

Reference #: 1FDUF5GY5GEA75486

Order #: _____

Inspected On: 08/23/16 6:56 AM CDT

Total Score: _____

Comments: _____

Michigan Shop Service Tech 1

Car Carrier-J13768

* Year: 2016

* Make: Ford

* Model: F550SD

* Engine Make: Triton

* Engine Model: 6.8L

* Horse Power: 362

* Fuel Type: Gasoline

* Transmission Type: Automatic

* Transmission Brand: TorqShift

* Odometer Reading: 6676

* GVW: 19,500#

* GAWR - Front: 6,500#

GAWR - Pusher Axle: 14,706#

* Rear Axle Ratio: 4.88

* Cab Trim Package: XL

Rear Vision Camera System/Brand: No

Remote Keyless Entry: Yes

* Cab to Axle: 120"

* Wheel-Base: 201"

Wheel Type: Stainless Steel Wheel Simulators

* Cab Color ONLY: White

* Body Make: Chevron

* Body Length: 19' 6"

* Body Model: Steel

* Body Serial Number: 195C10S-08226-MC16

Body Width: 99"

* Beacon/Lightbar Make: Code 3

* Beacon/Lightbar Model: Code 3 LED-X 2100

Directional Lightbar/Brand: No

Work Lights In Lightbar: Yes

* Side Puller Make: No

PTO Type: Hot Shift

Switch Panel & # Of Switches: In Dash - 4

Throttle: Yes In Cab

* Bed/Side Puller/Pylon Color ONLY: Black

* Brake Type: Hydraulic

* Suspension Type: Spring

* Air Compressor-FOR Brake System: No

Engine Brake: No

Air Dryer: No

* Air Conditioning: Yes

* Radio: AM/FM/CD/MP3

Navigation System/Brand: No

* Driver Seat: Split Cloth Seat w/Head Rests & Center Console

Windows: Power

Door Locks: Power

Window Deflectors: No

Owner:		Location:	
Rear Sliding Window:	No	Remote Control:	No
Cruise Control:	Yes	Pylon/Cab Guard:	Standard Steel
Tilt Steering Wheel:	Yes	Work Lights:	No
Air Horn:	No	Stop/Turn/Tail On Pylon:	Yes
Flooring:	Rubber or Vinyl	Extra Lights on BED/Where:	No
Floor Mats:	No	Crossmembers (Steel beds only):	6" Spacing
Bug Shield:	No	Bed Mounted D-Rings & #:	NA
Sunvisor:	No	Stake Pockets & #:	NA
* Bumper:	Chrome	Key Slots & #:	Yes 6 Key Slots
Grille:	Chrome	Bed Floor Type:	Steel
Front Tow Hooks:	Yes 2	Toolbox System/Where:	1-48" Steel - LH Side
Engine Block Heater:	No	Open Top Storage & Size:	No
Extra Lights on CAB/Where:	No	Dri-Dek In Toolboxes:	No
Jumper Cable Plug/Where:	Yes-Front Bumper	Air Hose Reel/Mounted Where:	No
Jumper Cable:	Yes	Auxiliary Air Compressor:	No
Running Boards/Nerf Bars:	Yes Running Boards	Snatch Blocks:	None
Mirrors:	Power/Heated/Lighted Swing Out	V-Chain/V-Strap Assemblies:	Yes V-Chain Assembly
Additional Mirrors:	Convex Mirrors	J-Chains & #:	Yes 1 Set
Spot Light:	None	Straps/Rachets:	Yes Both
Vertical Exhaust Stack:	No	Fire Extinguisher:	Yes
Cab Roof Marker Lights:	Yes	Warning Triangle Kit:	Yes
Tread Type Rear:	Mud & Snow	Tow Light System:	SL-9 LED
* Tire Size-Front:	225/70R19.5	Dual Controls:	Yes
Tire Depth-Front:	16/32	Front/Rear Safety Chains:	Yes Both
* Tire Size-Rear Axle:	225/70R19.5	Light Plug Ins:	Yes CR6
Tire Depth-Rear Axle:	16/32	Hook Up Lights:	Yes
Top Hat Kit:	No	* Wheel Lift/Wheel Lift Arms:	Yes with L-Arms
Lug Nut Covers:	No	Wheel Lift Style:	Basic L-Arm Style
Sub-Frame Finish:	Painted	Live Air Hook Up/Where:	No
Dump Angle:	Normal	Gas Cans/Holders/Where:	No
Dock Stabilizer:	No	Trash Cans/Holders/Where:	No
Side Rails:	Steel Removable	Self Loading Dollies:	No
Rub-Rails:	No	Go-Jaks:	No
# of Winches:	1	Trailer Hitch:	Built-In
Winch Brand:	Ramsey	Special Equipment Storage/Where:	No
Winch Capacity:	8,000# Worm Type		
Winch Clutch Release:	Yes Mechanical		
Winch Work Lights:	Yes		
Cable Tensioner:	Yes		
Cable Roller Guide:	Yes		

Inspector Name	Status	Comments
Enter name here	Jeff/Andy	
Engine Check	Status	Comments

Owner: _____

Location: _____

Engine Check	Status	Comments
Ability to Start	Starts Normally	
Engine Blow-By Check	No Noticeable Blow-By Issue	
Engine Oil Leaks	No Oil Leaks Observed	
Engine Noise	Engine sounds are normal	
Engine Warning Lights	No Check Engine Lights are on	
Engine Water Leaks	No Water Leaks	
Performance	Performs Normally	
Engine Mounts	In Good Condition	
Other Engine Notes		
Engine Brake		
Batteries	Status	Comments
Condition of Cables	In Good Condition	
Condition of Batteries	In Good Condition	
Load Test	Pass	
Cooling System	Status	Comments
Radiator	In Good Condition	-Some debris in fins Find blown out
Fan	In Good Condition	
Fan Clutch	In Good Condition	
Fan Shroud	In Good Condition	
Water Hoses	In Good Condition	
Fan Belt	In Good Condition	
Other Cooling Condition Notes		
Automatic Transmission Check	Status	Comments
Transmission Operation	Transmission Operates Normally	
Other Transmission Notes		
Manual Transmission Check	Status	Comments
Shifting		
Clutch Operation		
Throw-Out Bearing		
Transmission Noise		
Other Transmission Notes		
Overall Body Condition	Status	Comments
Overall Condition	Excellent	
Other Overall Body Condition notes		
Cab Exterior	Status	Comments
Hood	Excellent Condition	
Right Fender	Excellent Condition	
Left Fender	Excellent Condition	
Grille	In Excellent Condition	
Back of Cab	Excellent Condition	
Driver Side Door	Excellent Condition	
Passenger Side Door	Excellent Condition	
Roof	Excellent Condition	
Other Cab Exterior Notes		
Fuel Tank Appearance	In Good Condition	
Entry Steps	In Good Condition	

Cab Exterior	Status	Comments
Head-Light Doors	In Good Condition	
Battery Box		
Driver Side Door Hinges	In Good Condition	
Passenger Side Door Hinges	In Good Condition	
Front Bumper	Status	Comments
Factory Front Bumper	In Excellent Condition	
Front Push Bumper		
Glass Condition	Status	Comments
Windshield	Good Condition	
Driver Side Window	Good Condition	
Passenger Side Window	Good Condition	
Back Window	Good Condition	
Other Glass Condition Notes		
Overall Interior Condition	Status	Comments
Overall Condition	Excellent	
Other Overall Interior Notes		
Interior Condition	Status	Comments
Drivers Seat	Excellent Condition	
Passenger Seat	Excellent Condition	
Rear Seat	Excellent Condition	
Floor Mat	Excellent Condition	
Instrument Cluster	Excellent	
Dash	In Excellent Condition	
Door Panels	In Excellent Condition	
Electric Door Locks	Excellent Condition	
Other Interior Condition Notes		
Electric Windows	Operate Properly	
Door Handles	In Good Condition	
Air Vents	In Good Condition	
Headliner	In Excellent Condition	
Other Interior Notes		
Door Seals	In Good Condition	
Floor Mats		
Seat Belts	In Good Condition	
Windshield Wipers	Status	Comments
Wiper Arms	In Good Condition	
Wiper Blades	In Good Condition	
Washer Tank	In Good Condition	
Washer Control Switch	In Good Condition	
Heating	Status	Comments
Heater Controls	In Good Condition	
Fan Motor	Excellent Condition	
Heater	Heats Appropriately	
Other Heat Notes		
Air Conditioning	Status	Comments
Overall Condition	In Good Operating Condition	
Air Conditioning Controls	In Good Condition	
Electrical System-Chassis	Status	Comments

Owner: _____

Location: _____

Electrical System-Chassis	Status	Comments
Interior lights	All Interior Light Operate	
Turn Signals	Operate Normally	
Head Lights	Operate Normally	
Alternator	Performs Normally	
Guages	All Gauges Perform Properly	
Dash Lights	Dash Lights Perform Normally	
Cab Marker Lights	Marker Lights Perform Normally	
Back-Up Lights	Operate Normally	
Back-Up Alarm	Performs Normally	
4-Way Flashers	Performs Normally	
Windshield Wipers	Perform Normally	
Other Electrical System Notes		
Cruise Control	Operates Normally	
Engine Throttle	Operates Normally (Note Type)	
Drive-Line	Status	Comments
U-Joints	In Good Condition	
Rear Differential	In good condition	
Transfer Case		
Other Drive-Line Notes		
Hanger Bearings	In Excellent Condition	
Brakes	Status	Comments
Air Compressor		
System Air Leaks		
Air Dryer		
Applied Brakes	Brake apply normally	
Brake Adjusters		
Air Lines		
Low Air Pressure Warning		
Front Brake Drums		
Front Drive Axle Brake Drums		
Front Brake Calipers	In Good Condition	
Front Brake Linings	80% or Better	
Pusher Axle Brake Drums		
Pusher Axle Brake Linings		
Front Drive Axle Brake Linings		
Rear Drive Axle Brake Drums		
Rear Brake Calipers	In Good Condition	
Rear Drive Axle Brake Linings	80% or Better	
Emergency Brake	Performs Normally	
ABS Light	Showing Normal (Not on)	
Brake Pedal Pads	In Good Condition	
Other Brake Notes		
Shock Absorbers	Status	Comments
Front Shocks	In Good Condition	
Rear Front Shocks	In Good Condition	
Wheels	Status	Comments

Wheels	Status	Comments
Front Axle Rims/Wheels	Wheel In Good Condition	
Pusher Axle Rims/Wheels		
Front Drive Axle Rims/Wheels		
Front Drive Axle Nuts and Studs (2) (2)		
Rear Drive Axle Rims/Wheels	Wheel In Good Condition	
Fronts Axle Nut and Studs	In Good Condition	
Pusher Axle Nut and Studs		
Rear Drive Axle Nuts and Studs	In Good Condition	
Wheel Simulators Front Axle	In Excellent Condition	
Wheel Simulators Pusher Axle		
Wheel Simulators Front Drive Axle		
Wheel Simulators Rear Drive Axle	In Excellent Condition	
Aluminum Wheels Front Axle		
Aluminum Wheels Pusher Axle		
Aluminum Wheels Front Drive Axle		
Aluminum Wheels Rear Drive Axle		
Wheel Hubs	Status	Comments
Front Wheel Seals		
Pusher Axle Wheel Seals		
Front Drive Axle Wheel Seals		
Rear Drive Axle Wheel Seals	In Good Condition	
Oil Filled Hubs Front Axle		
Oil Filled Hubs Pusher Axle		
Oil Filled Hubs Front Drive Axle		
Oil Filled Hubs Rear Drive Axle		
Front Wheel Bearings	Checked In Good Condition	
Front Drive Axle Wheel Bearings		
Pusher Axle Wheel Bearings		
Rear Drive Axle Wheel Bearings	Not Adjusted but No Issue Visible	
Tires	Status	Comments
Front Axle	In Excellent Condition 75% tread or Better	
Pusher Axle		
Front Drive Axle		
Rear Drive Axle	In Excellent Condition 75% tread or Better	
Notes on Tires		
Exhaust System	Status	Comments
Manifold	In Good Condition	
Exhaust Tubing	In Good Condition	
Muffler	In Good Condition	
DPF System		
Emnsions Warning Light		
Exhaust Shield	In Good Condition	
Exhaust Stack		
Exhaust Mounting Bracket	In Good Condition	
Frame	Status	Comments

Owner: _____

Location: _____

Frame	Status	Comments
Integrity of Frame	In good Condition	
Suspension	Status	Comments
Air Bags		
Air Leaks		
Air Lines		
Spring Packs	In Good Condition	
Front Spring Hangars	In Good Condition	
Rear Spring Hangars	In Good Condition	
Radius Arms	In Good Condition	
Rear Suspension Bushings	In Good Condition	
Air Leveling Valve		
Steering and Front Axle	Status	Comments
Steering Pump	Operates Normally	
Steering Lines	In Good Operating Condition	
Steering Sector	In Good Operating Condition	
King Pins/Ball Joints	In Good Condition	
Steering Shaft	In Good Condition	
Pitman Arm	In Good Condition	
Drag Link	In Good Condition	
Tie Rod	In Good Condition	
Toe in Check	Not Checked	
4x4 Hubs		
Steering Wheel	Steering Wheel in Good Cosmetic Condition	
Steering Wheel Position	Steering Wheel In Correct Postion When Driven	
Fuel System	Status	Comments
Fuel Gauge	Works Normally	
Fuel Tank	In Good Condition	
Fuel Fill	Fills slowly	
Fuel Lines	In Good Condition	
Fuel Filter	Not Replaced	
Glow Plugs or Exhaust Heater	Status	Comments
Glow Plug Operation		
Intake Manifold Heater		
Fluids	Status	Comments
Windshield Washer	Full	
Engine Oil	Changed and Full	
Radiator Anti-Freeze	Full and Tested to 20 Below	
Transmission Fluid	Full	
Transfer Case Oil		
Front Drive Axle		
Rear Drive Axle	Full	
Battery Acid Levels		
Hydraulic Oil	At Proper Level	
Brake Fluid	At Proper Level	
Power Steering Fluid	At Proper Level	
Winch 1 Oil	Filled to Prope Level	
Winch 2 Oil		

Fluids	Status	Comments
Winch 3 (Above Cab) Oil		
Filters	Status	Comments
Water Filter		
Engine Oil Filter	Replaced	
Transmission Oil Filter		
Fuel Filter	Original (Not replaced)	
Carrier Hydraulic System	Not Changed	
Engine Air Filter	Replaced	-Replace
Chassis Lubrication Points	Status	Comments
King Pins/Ball Joints	Freshly Greased	
Tie-Rods Ends	Freshly Greased	
Steering Shaft Bearing		
Drag Link		
Clutch Linkage		
Throw-Out Bearing		
Drive-Line U-Joints		
S-Cam Shafts		
Slack Adjusters		
Spring Hangars		
Door Locks and Hinges	Lubricated	
Overall Car Carrier Condition	Status	Comments
Overall Condition	Excellent	
Carrier Deck	Status	Comments
Aluminum Deck Condition		
Steel Deck Condition	Has Minor Scratches	
Aluminum Deck Side-rails		
Steel Deck Side-rails	In Excellent Condition	
Steel Deck Side-rails Paint	In Good Condition	
Aluminum Tail Section		
Rear Rollers		
Re-movable Side Rails Steel	In Good Condition	
Re-movable Side Rails Aluminum		
Anti-Tilt Protection System	In Good COndition	
Power Take-Off	Status	Comments
Operation	Operates Normally	
Oil Leaks	No Oil Leaks	
PTO Warning Light	In Good Operating Condition	
Shifting Mechanism	Electrical Switch Working Properly	
Air Leaks		
Hyraulic Pump	Status	Comments
Oil Leaks	No Oil Leaks	
Operation	Pump Operates Normally	
Pump Pressure	Tested to 2500#	
Pump Flow	Not Tested	
Control Valve	Status	Comments
Oil Leaks	No Oil Leaks	
Operation	Operates Normally	
Control Levers and Rods	In Excellent Condition	
Control Box	In Excellent Condition	
Knobs	In Excellent Condition	

Owner: _____

Location: _____

Control Valve	Status	Comments
Control Decals	In Good Condition	
Hydraulic System Hoses	Status	Comments
Oil Leaks	In Operating Condition	
Hydraulic System Leaks	Status	Comments
Winch Hoses	No Oil Leaks	
Lift Cylinder Hoses	No Oil Leaks	
Extension Cylinder Hoses	No Oil Leaks	
Wheel-Lift Tilt Cylinder Hoses	No Oil Leaks	
Wheel-Lift Extend Cylinder Hoses (2)	No Oil Leaks	
Hydraulic Pump Hoses	No Oil Leaks	
Hydraulic Filter	No Oil Leaks	
Bed Lift Cylinders	No Oil Leaks	
Extend Cylinder	No Oil Leaks	
Wheel-Lift Tilt Cylinder	No Oil Leaks	
Wheel-Lift Extend Cylinder	No Oil Leaks	
Wheel-Lift Claw Cylinder Drivers Side		
Wheel-Lift Claw Cylinder Passenger Side		
Pylon	Status	Comments
Overall Condition	In Good Condition with Minor Scratches/Dents	
Winch	Status	Comments
Oil Leaks	No Oil Leaks	
Free-Wheel Mechanism Winch 1	Operates Normally	
Free-Wheel Mechanism Winch 2		
Free-Wheel Mechanism Winch 3		
Housing Winch 1	In Excellent Condition	
Housing Winch 2		
Housing Winch 3		
Operation Without Load	Performs Normally	
Operation Without Load Notes		
Test Operation Loaded		
Test Operation Notes		
Winch 1 Cable	Replaced With New	
Winch 2 Cable		
Winch 3 Cable		
Cable Tensioner	In Good Condition	
Wheel-Lift	Status	Comments
L-Arms/Scoops	In Excellent Condition	
L-Arm Straps	In Good Condition	
L-Arm Storage	In Good Condition	
Driver Side Claw		
Passenger Side Claw		
Driver Side Slide Tray	In Excellent Condition	
Passenger Side Slide Tray	In Excellent Condition	
Passenger Side Slide Tray Locks	In Excellent Condition	
Driver Side Slide Tray Locks (2)	In Excellent Condition	
Driver Side Front Stops (Vulcan)		
Passenger Side Front Stops (Vulcan)		
Driver Side L-Arm Swivel		

Wheel-Lift	Status	Comments
Passenger Side L-Arm Swivel (2)		
Center Pivot Pin and Bushing	In Excellent Condition	
Wheel-Lift Cross-Bar	In Excellent Condition	
Pins and Bushings	In Excellent Condition	
Extension Tube	In Excellent Condition	
Outer Wheel-Lift Assembly	In Excellent Condition	
Wheel-Lift Swivel Lock Pins		
Wheel-Lift Swivel Lock Pins (2)		
Scoop Locking Pins and Chains		
Driver Side Claw Cylinders		
Wear Pads	In Excellent Condition	
Carrier Electrical Systems	Status	Comments
Switch Panel	In Excellent Condition	
Overall Wiring Condition	In Excellent Condition	
Bed Wiring Harness Condition	In Excellent Condition	
Junction Boxes Condition	In Excellent Condition	
Marker Lights	In Excellent Condition	
Driver Side Turn Signals Upper	In Excellent Condition	
Passenger Side Turn Signals Upper	In Excellent Condition	
Driver Side Turn Signals Upper Lower	In Excellent Condition	
Passenger Side Turn Signals Lower	In Excellent Condition	
Extra Warning Lights		
Extra Clearance Lights		
UpperWork Lights	In Excellent Condition	
Lower Work Lights	In Excellent Condition	
Work Lights Mounted Near Winch	In Excellent Condition	
Beacon Light	In Excellent Condition	
Tow Light Plug at Tail-Board	In Excellent Condition	
License Plate Light	In Excellent Condition	
Tool Boxes	Status	Comments
Box Driver Side 1	In Excellent Condition	
Box Driver Side 2		
Box Passenger Side 1		
Box Passenger Side 2		
Fenders	Status	Comments
Drivers Side		
Passenger Side		
Carrier Components	Status	Comments
Bed Hold-Downs	In Excellent Condition	
Rear Bed Mounting (Pivot Pin)	In Excellent Condition	
Driver Side Tail-Light Housing	In Excellent Condition	
Passenger Side Tail-Light Housing (2)	In Excellent Condition	
Rear Tail Section	In Excellent Condition	
Body Lubrication Points	Status	Comments
Bed Pivot Pin	Freshly Greased	
Lift Cylinder Pins	Freshly Greased	
Wheel-lift Tilt Pin	Freshly Greased	

Owner: _____

Location: _____

Body Lubrication Points	Status	Comments
Wheel-Lift Pivot Pin	Freshly Greased	
Wheel-Lift Upper Slide Pads	Freshly Greased	
Wheel-Lift Lower Slide Pads	Freshly Greased	
Deck Slide Back Wear Pads	Freshly Greased	
Tool Box Door Hinges and Locks	Lubed	
Carrier Chains	Status	Comments
Front Safety Chains	In Excellent Condition	
Rear Safety Chains	In Excellent Condition	
V-Chains Chains	In Excellent Condition	
V-Chains Straps		
Mud-Flaps	Status	Comments
Mounting Brackets	In Good Condition	
Mud-Flap	In Good Condition	