



Zip's Truck Equipment

316 W. Milwaukee Street
New Hampton, Iowa 50659
Phone: 641-394-3166
Fax: 641-394-4044



FIELD iD

Visual Inspection

Page: 1 of 7

Customer: _____

Address: _____

Serial No: J12039

Equipment Type: Car Carrier

Event Performed: Car Carrier Inspection

Result: Pass

Inspected By: _____

Division: _____

Location: _____

Phone: _____

Reference #: 1HTMPAFM15H681911

Order #: _____

Inspected On: 05/15/15 6:56 AM CDT

Total Score: _____

Comments: _____

Iowa Shop Service Tech 1

Car Carrier-J12039

* Year: 2005

* Make: International

* Model: 4200

* Engine Model: VT365

* Fuel Type: Diesel

* Transmission Type: Automatic

* Transmission Brand: Allison

* Odometer Reading: 147237

Hour Meter Reading: 8129

* GVW: 25,500#

* GAWR Front: 8,000#

* GAWR Rear: 17,500#

Rear Vision Camera System/Brand: No

Remote Keyless Entry: No

* Cab to Axle: 150"

* Wheel-Base: 216

Wheel Type: Stainless Steel Wheel Simulators

* Cab Color ONLY: White

* Body Make: Jerr-Dan

* Body Length: 21'

* Body Model: Steel

* Body Serial Number: 58907

Body Width: 96"

* Beacon/Lightbar Make: Jerr-Dan

* Beacon/Lightbar Model: SAE-WW3-95 Amber Rotators

Directional Lightbar/Brand: No

Work Lights In Lightbar: Yes

* Side Puller Make: No

PTO Type: Hot Shift

Switch Panel & # Of Switches: In Dash - 6

In Cab Throttle: No

* Bed/Side Puller/Pylon Color ONLY: Black

* Brake Type: Hydraulic

* Suspension Type: Spring

* Air Compressor-FOR Brake System: Yes

Engine Brake: No

Air Dryer: No

* Air Conditioning: Yes

* Radio: AM/FM/CD

Navigation System/Brand: No

* Driver Seat: Vinyl Air Ride High Back w/rh armrest

Passenger Seat: Vinyl 2 Man High Back

Windows: Power

Door Locks: Power

Window Deflectors: No

Rear Sliding Window: No

Cruise Control: Yes

Owner:			Location:		
Tilt Steering Wheel:	Yes	Cable Roller Guide:	Yes		
Air Horn:	Yes	Remote Control:	On Winch		
Flooring:	Rubber or Vinyl	Pylon/Cab Guard:	Standard Steel		
Floor Mats:	No	Work Lights:	No		
Bug Shield:	No	Stop/Turn/Tail On Pylon:	Yes		
Sunvisor:	No	Extra Lights on BED/Where:	No		
* Bumper:	Chrome	Crossmembers (Steel beds only):	12" Spacing		
Grille:	Chrome	Bed Mounted D-Rings & #:	NA		
Front Tow Hooks:	Yes 2	Stake Pockets & #:	NA		
Engine Block Heater:	Yes	Key Slots & #:	Yes 4 Key Slots		
Extra Lights on CAB/Where:	Yes - Strobes in headlights	Bed Floor Type:	Steel		
Jumper Cable Plug/Where:	No	Toolbox System/Where:	1-36" Steel - RH 1-48" Steel - LH		
Jumper Cable:	No	Open Top Storage & Size:	Yes - 48" w/ stainless face		
Cab Fenders:	Fiberglass Fenderettes	Dri-Dek In Toolboxes:	Yes		
Running Boards/Nerf Bars:	No	Air Hose Reel/Mounted Where:	No		
Mirrors:	Stainless Steel Power/Heated/Lighted Swing Out	Auxiliary Air Compressor:	No		
Additional Mirrors:	Convex Mirrors	Snatch Blocks:	None		
Spot Light:	None	V-Chain/V-Strap Assemblies:	Yes V-Chain Assembly		
Fuel Tank/Where:	1 Steel - Right side	J-Chains & #:	Yes 1 Set		
Fuel Tank Gallons:	55	Straps/Rachets:	No		
Vertical Exhaust Stack:	No	Fire Extinguisher:	No		
Cab Roof Marker Lights:	Yes	Warning Triangle Kit:	No		
Tread Type Rear:	Mud & Snow	Tow Light System:	No		
* Tire Size-Front:	245/70R19.5	Dual Controls:	Yes		
Tire Depth-Front:	12/32	Front/Rear Safety Chains:	Yes Both		
* Tire Size-Rear Axle:	245/70R19.5	Light Plug Ins:	Yes CR6		
Tire Depth-Rear Axle:	13/32	Hook Up Lights:	Yes		
Top Hat Kit:	No	* Wheel Lift/Wheel Lift Arms:	Yes with L-Arms		
Lug Nut Covers:	Yes	Wheel Lift Style:	Basic L-Arm Style		
Sub-Frame Finish:	Painted	Live Air Hook Up/Where:	No		
Dump Angle:	Normal	Gas Cans/holders/Where:	No		
Dock Stabilizer:	No	Trash Cans/holders/Where:	No		
Side Rails:	Steel Tube Fixed	Self Loading Dollies:	No		
Rub-Rails:	No	Go-Jaks:	No		
# of Winches:	1	Trailer Hitch:	Built-In		
Winch Brand:	Ramsey	Special Equipment Storage/Where:	No		
Winch Capacity:	8,000# Worm Type	Other Equipment:	Strobes on rear tailboard		
Winch Clutch Release:	Yes Mechanical				
Winch Work Lights:	No				
Cable Tensioner:	Yes				

Owner: _____

Location: _____

Inspector Name	Status	Comments
Enter name here	Andy / Josh	
Engine Check	Status	Comments
Ability to Start	Starts Normally	-Hauled here from Michigan for a no start complaint. Inspected and found no ICP pressure. Replaced high pressure pump and regulator.
Engine Blow-By Check	Has some Blow-By	-No repair -Minimal blow by
Engine Oil Leaks	Oil leak observed (see Comments)	-No repair -Oil pan leak
Engine Noise	Engine sounds are normal	
Engine Warning Lights	No Check Engine Lights are on	
Engine Water Leaks	No Water Leaks	
Performance	Performs Normally	
Engine Mounts	In Good Condition	
Other Engine Notes		
Engine Brake		
Batteries	Status	Comments
Condition of Cables	Corroded Need Cleaning	-Repaired -Need to be cleaned
Condition of Batteries	In Good Condition	
Load Test	Pass	
Cooling System	Status	Comments
Radiator	In Good Condition	
Fan	In Good Condition	
Fan Clutch	In Good Condition	
Fan Shroud	In Good Condition	
Water Hoses	In Good Condition	
Fan Belt	In Good Condition	
Other Cooling Condition Notes		
Automatic Transmission Check	Status	Comments
Transmission Operation	Transmission Operates Normally	
Other Transmission Notes		
Manual Transmission Check	Status	Comments
Shifting		
Clutch Operation		
Throw-Out Bearing		
Transmission Noise		
Other Transmission Notes		
Overall Body Condition	Status	Comments
Overall Condition	Good	
Other Overall Body Condition notes	Minor scratches and paint chips	
Cab Exterior	Status	Comments
Hood	Scratched	-No repair -Minor scratches and paint chips
Right Fender	Dented or Cracked	-No repair -Bottom inside chunk missing
Left Fender	Good Condition	
Grille	In Excellent Condition	
Back of Cab	Excellent Condition	

Cab Exterior	Status	Comments
Driver Side Door	Scratched	-No repair -Few small scratches
Passenger Side Door	Good Condition	
Roof	Good Condition	
Other Cab Exterior Notes		
Fuel Tank Appearance	In Good Condition	
Entry Steps	In Need of Paint	-No repair -Rust bubbling. Paint missing
Head-Light Doors	In Good Condition	
Battery Box	In Good Condition	
Driver Side Door Hinges	Worn - Useable	-No repair -Slightly worn causing small wind leak
Passenger Side Door Hinges	In Good Condition	
Front Bumper	Status	Comments
Factory Front Bumper	Dented/ Scratched or Rusted	-No repair -Small dents little rust
Front Push Bumper		
Glass Condition	Status	Comments
Windshield	Good Condition	
Driver Side Window	Good Condition	
Passenger Side Window	Good Condition	
Back Window	Good Condition	
Other Glass Condition Notes		
Overall Interior Condition	Status	Comments
Overall Condition	Good	
Other Overall Interior Notes		
Interior Condition	Status	Comments
Drivers Seat	Fair Condition	-No repair -Small rip on bottom cushion
Passenger Seat	Good Condition	-No repair -Small tear in back
Rear Seat		
Floor Mat	Worn or torn and in need of replacement	-No repair -Ripped at doghouse dr side
Instrument Cluster	Excellent	
Dash	In Excellent Condition	
Door Panels	In Excellent Condition	
Electric Door Locks	Excellent Condition	
Other Interior Condition Notes		-No repair -LH speaker grille missing
Electric Windows	Operate Properly	
Door Handles	In Good Condition	
Air Vents	In Good Condition	
Headliner	Sagging or Loose	-No repair -Sagging
Other Interior Notes		
Door Seals	In Good Condition	
Floor Mats	Missing or In Need of Replacement	-No repair -No floor mats
Seat Belts	In Good Condition	
Windshield Wipers	Status	Comments
Wiper Arms	In Good Condition	

Owner: _____

Location: _____

Windshield Wipers	Status	Comments
Wiper Blades	In Need of Repair	-No repair -Streaky
Washer Tank	In Good Condition	
Washer Control Switch	In Good Condition	
Heating	Status	Comments
Heater Controls	In Good Condition	
Fan Motor	Excellent Condition	
Heater	Heats Appropriately	
Other Heat Notes		
Air Conditioning	Status	Comments
Overall Condition	In Good Operating Condition	
Air Conditioning Controls	In Good Condition	
Electrical System-Chassis	Status	Comments
Interior lights	Problem with Interior Lights (see Comments)	-Repaired -RH underdash light inop
Turn Signals	Operate Normally	
Head Lights	Operate Normally	
Alternator	Performs Normally	
Gauges	All Gauges Perform Properly	
Dash Lights	Dash Lights Perform Normally	
Cab Marker Lights	Marker Lights Perform Normally	
Back-Up Lights	Operate Normally	
Back-Up Alarm	Performs Normally	
4-Way Flashers	Performs Normally	
Windshield Wipers	Perform Normally	
Other Electrical System Notes		
Cruise Control	Operates Normally	
Engine Throttle	Operates Normally (Note Type)	
Drive-Line	Status	Comments
U-Joints	Loose or Worn	-Inspected-ok -2 rear u joints have movement
Rear Differential	In good condition	
Transfer Case		
Other Drive-Line Notes		
Hanger Bearings	In Excellent Condition	
Brakes	Status	Comments
Air Compressor	In Good Condition	
System Air Leaks		
Air Dryer		
Applied Brakes	Brake apply normally	
Brake Adjusters		
Air Lines		
Low Air Pressure Warning	N/A	
Front Brake Drums		
Front Drive Axle Brake Drums		
Front Brake Calipers	In Good Condition	
Front Brake Linings	60 or Better	

Brakes	Status	Comments
Pusher Axle Brake Drums		
Pusher Axle Brake Linings		
Front Drive Axle Brake Linings	80% or Better	
Rear Drive Axle Brake Drums		
Rear Brake Calipers	In Good Condition	
Rear Drive Axle Brake Linings		
Emergency Brake	Performs Normally	
ABS Light	Showing Normal (Not on)	
Brake Pedal Pads	In Good Condition	
Other Brake Notes		
Shock Absorbers	Status	Comments
Front Shocks	In Good Condition	
Rear Front Shocks		
Wheels	Status	Comments
Front Axle Rims/Wheels	Wheel In Good Condition	
Pusher Axle Rims/Wheels		
Front Drive Axle Rims/Wheels		
Front Drive Axle Nuts and Studs (2) (2)		
Rear Drive Axle Rims/Wheels	Wheel In Good Condition	
Fronts Axle Nut and Studs	In Good Condition	
Pusher Axle Nut and Studs		
Rear Drive Axle Nuts and Studs	In Good Condition	
Wheel Simulators Front Axle	Damaged	-No repair -Both front simulators dented and scratched
Wheel Simulators Pusher Axle		
Wheel Simulators Front Drive Axle		
Wheel Simulators Rear Drive Axle	In Good Condition	
Aluminum Wheels Front Axle		
Aluminum Wheels Pusher Axle		
Aluminum Wheels Front Drive Axle		
Aluminum Wheels Rear Drive Axle		
Wheel Hubs	Status	Comments
Front Wheel Seals	In Good Condition	
Pusher Axle Wheel Seals		
Front Drive Axle Wheel Seals		
Rear Drive Axle Wheel Seals	In Good Condition	
Oil Filled Hubs Front Axle	In Good Condition	
Oil Filled Hubs Pusher Axle		
Oil Filled Hubs Front Drive Axle		
Oil Filled Hubs Rear Drive Axle	In Good Condition	
Front Wheel Bearings	Checked In Good Condition	
Front Drive Axle Wheel Bearings		
Pusher Axle Wheel Bearings		
Rear Drive Axle Wheel Bearings		
Tires	Status	Comments

Owner: _____

Location: _____

Tires	Status	Comments
Front Axle	In Excellent Condition 75% tread or Better	-No repair -Irregular wear on outer edge
Pusher Axle		
Front Drive Axle		
Rear Drive Axle	In Excellent Condition 75% tread or Better	
Notes on Tires		
Exhaust System	Status	Comments
Manifold	In Good Condition	
Exhaust Tubing	In Good Condition	
Muffler	In Good Condition	
DPF System		
Emnsions Warning Light		
Exhaust Shield		
Exhaust Stack		
Exhaust Mounting Bracket	In Good Condition	
Frame	Status	Comments
Integrity of Frame	In good Condition	
Suspension	Status	Comments
Air Bags		
Air Leaks		
Air Lines		
Spring Packs	In Good Condition	
Front Spring Hangars	In Good Condition	
Rear Spring Hangars	In Good Condition	
Radius Arms		
Rear Suspension Bushings	In Good Condition	
Air Leveling Valve		
Steering and Front Axle	Status	Comments
Steering Pump	Operates Normally	
Steering Lines	In Good Operating Condition	
Steering Sector	In Good Operating Condition	
King Pins/Ball Joints	Need Replacing	-Repaired -Need replacing
Steering Shaft	In Good Condition	
Pitman Arm	In Good Condition	
Drag Link	In Good Condition	
Tie Rod	In Good Condition	
Toe in Check	Not Checked	
4x4 Hubs		
Steering Wheel	Steering Wheel in Good Cosmetic Condition	
Steering Wheel Position	Steering Wheel Not in Correct Position When Driven	-Centered -A hair to the left
Fuel System	Status	Comments
Fuel Gauge	Works Normally	
Fuel Tank	In Good Condition	
Fuel Fill	Fills Normally	
Fuel Lines	In Good Condition	
Fuel Filter	Not Replaced	

Glow Plugs or Exhaust Heater	Status	Comments
Glow Plug Operation	Glow Perform Normally	
Intake Manifold Heater		
Fluids	Status	Comments
Windshield Washer	Not Checked	
Engine Oil	Appears That It Needs to be Changed	-Needs change
Radiator Anti-Freeze	Full and Tested to 20 Below	
Transmission Fluid	Low	
Transfer Case Oil		
Front Drive Axle	Full	
Rear Drive Axle		
Battery Acid Levels		
Hydraulic Oil	Not Checked	-No repair-full -Sight glass painted
Brake Fluid	At Proper Level	
Power Steering Fluid	At Proper Level	
Winch 1 Oil	Filled to Prope Level	
Winch 2 Oil		
Winch 3 (Above Cab) Oil		
Filters	Status	Comments
Water Filter		
Engine Oil Filter	Original (Not replaced)	
Transmission Oil Filter	Original (Not replaced)	
Fuel Filter	Original (Not replaced)	
Carrier Hydraulic System	Not Changed	
Engine Air Filter	Inspected in Good Condition	
Chassis Lubrication Points	Status	Comments
King Pins/Ball Joints	Appears Dry	
Tie-Rods Ends	Appears Dry	
Steering Shaft Bearing	Appears To have Been Well Greased	
Drag Link	Appears To have Been Well Greased	
Clutch Linkage		
Throw-Out Bearing		
Drive-Line U-Joints	Appears To have Been Well Greased	
S-Cam Shafts		
Slack Adjusters		
Spring Hangars		
Door Locks and Hinges	Lubricated	
Overall Car Carrier Condition	Status	Comments
Overall Condition	Good	
Carrier Deck	Status	Comments
Aluminum Deck Condition		
Steel Deck Condition	Is Wash-Boarded	-No repair -Slight washboarding
Aluminum Deck Side-rails		
Steel Deck Side-rails	In Fair Condition	-No repair -Scratches dents slight bending
Steel Deck Side-rails Paint	Significant Scratches or Marks	-No repair -Beat up
Aluminum Tail Section		
Rear Rollers		

Owner: _____

Location: _____

Carrier Deck	Status	Comments
Re-movable Side Rails Steel		
Re-movable Side Rails Aluminum		
Anti-Tilt Protection System		
Power Take-Off	Status	Comments
Operation	Operates Normally	
Oil Leaks	No Oil Leaks	
PTO Warning Light	In Good Operating Condition	
Shifting Mechanism	Electrical Switch Working Properly	
Air Leaks		
Hydraulic Pump	Status	Comments
Oil Leaks	No Oil Leaks	
Operation	Pump Operates Normally	
Pump Pressure	Appears to Operate Bed Normally - Not Tested	
Pump Flow	Not Tested	
Control Valve	Status	Comments
Oil Leaks	No Oil Leaks	
Operation	Operates Normally	
Control Levers and Rods	Loose and Worn Pins and Rod Connections	-Trim housing -4/5 rods worn out. Pins bushings shafts and mounting tabs worn out
Control Box	In Excellent Condition	
Knobs	In Excellent Condition	
Control Decals	In Good Condition	
Hydraulic System Hoses	Status	Comments
Oil Leaks	In Operating Condition	
Hydraulic System Leaks	Status	Comments
Winch Hoses	No Oil Leaks	
Lift Cylinder Hoses	No Oil Leaks	
Extension Cylinder Hoses	No Oil Leaks	
Wheel-Lift Tilt Cylinder Hoses	No Oil Leaks	
Wheel-Lift Extend Cylinder Hoses (2)	Leaks Between Cylinders and Valve	-Repaired -Wet not dripping
Hydraulic Pump Hoses	No Oil Leaks	
Hydraulic Filter	No Oil Leaks	
Bed Lift Cylinders	No Oil Leaks	
Extend Cylinder	No Oil Leaks	
Wheel-Lift Tilt Cylinder	No Oil Leaks	
Wheel-Lift Extend Cylinder	No Oil Leaks	
Wheel-Lift Claw Cylinder Drivers Side		
Wheel-Lift Claw Cylinder Passenger Side		
Pylon	Status	Comments
Overall Condition	In Good Condition with Minor Scratches/Dents	
Winch	Status	Comments
Oil Leaks	No Oil Leaks	
Free-Wheel Mechanism Winch 1	Operates Normally	
Free-Wheel Mechanism Winch 2		
Free-Wheel Mechanism Winch 3		

Winch	Status	Comments
Housing Winch 1	In Excellent Condition	
Housing Winch 2		
Housing Winch 3		
Operation Without Load	Performs Normally	
Operation Without Load Notes		
Test Operation Loaded	Performs Normally	
Test Operation Notes		
Winch 1 Cable	In Good Condition	-Replaced clip -Missing safety clip.
Winch 2 Cable		
Winch 3 Cable		
Cable Tensioner	In Good Condition	
Wheel-Lift	Status	Comments
L-Arms/Scoops	In Excellent Condition	
L-Arm Straps	Missing	
L-Arm Storage	In Good Condition	
Driver Side Claw		
Passenger Side Claw		
Driver Side Slide Tray	In Good Condition	-Free'd up -Grid lock screw frozen
Passenger Side Slide Tray	In Good Condition	-Free'd up -Grid lock screw frozen
Passenger Side Slide Tray Locks	In Fair Condition	-Free'd up -Frozen
Driver Side Slide Tray Locks (2)	In Fair Condition	-Free'd up -Frozen
Driver Side Front Stops (Vulcan)		
Passenger Side Front Stops (Vulcan)		
Driver Side L-Arm Swivel		
Passenger Side L-Arm Swivel (2)		
Center Pivot Pin and Bushing	In Good Condition	
Wheel-Lift Cross-Bar	In Good Condition	
Pins and Bushings	In Good Condition	
Extension Tube	In Good Condition	
Outer Wheel-Lift Assembly	In Good Condition	
Wheel-Lift Swivel Lock Pins		
Wheel-Lift Swivel Lock Pins (2)		
Scoop Locking Pins and Chains		
Driver Side Claw Cylinders		
Wear Pads	In Good Condition	
Carrier Electrical Systems	Status	Comments
Switch Panel	In Good Condition	
Overall Wiring Condition	In Good Condition	
Bed Wiring Harness Condition	In Good Condition	
Junction Boxes Condition		
Marker Lights	Some Lights Inoperative	-Repaired -Rear red bed light driver side inop
Driver Side Turn Signals Upper	In Good Condition	
Passenger Side Turn Signals Upper	In Good Condition	
Driver Side Turn Signals Upper Lower	In Good Condition	
Passenger Side Turn Signals Lower	In Good Condition	

Owner: _____ Location: _____

Carrier Electrical Systems	Status	Comments
Extra Warning Lights	In Good Condition	
Extra Clearance Lights		
UpperWork Lights	In Good Condition	
Lower Work Lights	In Good Condition	
Work Lights Mounted Near Winch		
Beacon Light	In Good Condition	
Tow Light Plug at Tail-Board	In Good Condition	
License Plate Light	Lights Missing	-Installed light -Truck not set up for light
Tool Boxes	Status	Comments
Box Driver Side 1	In Good Condition	
Box Driver Side 2		
Box Passenger Side 1	In Good Condition	
Box Passenger Side 2		
Fenders	Status	Comments
Drivers Side		
Passenger Side		
Carrier Components	Status	Comments
Bed Hold-Downs	In Good Condition	
Rear Bed Mounting (Pivot Pin)	In Good Condition	
Driver Side Tail-Light Housing	In Good Condition	
Passenger Side Tail-Light Housing (2)	In Good Condition	
Rear Tail Section	In Good Condition	-No repair -Driver side chain holder bent
Body Lubrication Points	Status	Comments
Bed Pivot Pin		
Lift Cylinder Pins		
Wheel-lift Tilt Pin		
Wheel-Lift Pivot Pin		
Wheel-Lift Upper Slide Pads		
Wheel-Lift Lower Slide Pads		
Deck Slide Back Wear Pads		
Tool Box Door Hinges and Locks	Lubed	
Carrier Chains	Status	Comments
Front Safety Chains		
Rear Safety Chains	In Good Condition	
V-Chains Chains	In Good Condition	
V-Chains Straps	Missing	-Installed new -J chains missing
Mud-Flaps	Status	Comments
Mounting Brackets	In Good Condition	
Mud-Flap	In Good Condition	