



Zip's Truck Equipment

316 W. Milwaukee Street
New Hampton, Iowa 50659
Phone: 641-394-3166
Fax: 641-394-4044



Visual Inspection

Page: 1 of 7

Customer: _____

Address: _____

Serial No: J12050

Equipment Type: Car Carrier

Event Performed: Car Carrier Inspection

Result: Pass

Inspected By: _____

Division: _____

Location: _____

Phone: _____

Reference #: 2NKMHD6H84M060579

Order #: _____

Inspected On: 01/28/15 9:16 AM CST

Total Score: _____

Comments: _____

Michigan Shop Service Tech 1

Car Carrier-J12050

* Year: 2004

* Make: Kenworth

* Model: T300

* Engine Make: CAT

* Engine Model: C7

* Horse Power: 210

* Fuel Type: Diesel

* Transmission Type: Manual

* Transmission Brand: Eaton Fuller

* Transmission Model: 6 Speed

* Odometer Reading: 199821

Hour Meter Reading: 15867

* GVW: 26,000#

* Rear Axle Ratio: 5.57

Rear Vision Camera System/Brand: No

Remote Keyless Entry: No

* Cab to Axle: 150"

* Wheel-Base: 220

Wheel Type: Stainless Steel Wheel Simulators

* Cab Color ONLY: White/Gray/Orange/Black

* Body Make: Jerr-Dan

* Body Length: 21'

* Body Model: Steel

* Body Serial Number: 56993

Body Width: 96"

* Beacon/Lightbar Make: Federal Signal

* Beacon/Lightbar Model: AeroDynic

Directional Lightbar/Brand: No

Work Lights In Lightbar: Yes

* Side Puller Make: No

PTO Type: Manual Shift

Switch Panel & # Of Switches: Switch Panel - 3

In Cab Throttle: Yes

* Bed/Side Puller/Pylon Color ONLY: Black

* Brake Type: Hydraulic

* Suspension Type: Spring

* Air Compressor-FOR Brake System: No

Engine Brake: No

Air Dryer: No

* Air Conditioning: Yes

* Radio: AM/FM/CD

Navigation System/Brand: No

* Driver Seat: Cloth Air Ride High Back w/ Armrests

Passenger Seat: Cloth 2 Man

Windows: Manual Crank

Door Locks: Manual

Window Deflectors: No

Owner:		Location:	
Rear Sliding Window:	No	Remote Control:	No
Cruise Control:	Yes	Pylon/Cab Guard:	Standard Steel
Tilt Steering Wheel:	Yes Tilt/Telescopic	Work Lights:	No
Air Horn:	No	Stop/Turn/Tail On Pylon:	Yes
Flooring:	Carpet	Extra Lights on BED/Where:	No
Floor Mats:	No	Crossmembers (Steel beds only):	8" Spacing
Bug Shield:	No	Bed Mounted D-Rings & #:	NA
Sunvisor:	No	Stake Pockets & #:	NA
* Bumper:	Chrome	Key Slots & #:	Yes 4 Key Slots
Grille:	Chrome	Bed Floor Type:	Smooth Steel
Front Tow Hooks:	No	Toolbox System/Where:	1-36" Steel - Lt side 1-48" Rt side
Engine Block Heater:	No	Open Top Storage & Size:	No
Extra Lights on CAB/Where:	No	Dri-Dek In Toolboxes:	No
Jumper Cable Plug/Where:	Yes- Lt side behind lower step	Air Hose Reel/Mounted Where:	No
Jumper Cable:	No	Auxiliary Air Compressor:	No
Mirrors:	Heated Swing Out	Snatch Blocks:	None
Additional Mirrors:	Spot Mirrors Lt-8" Rt-7"	V-Chain/V-Strap Assemblies:	No
RH Down View Mirror, RH Peep Window:	Yes Both	J-Chains & #:	No
Spot Light:	None	Straps/Rachets:	No
Fuel Tank/Where:	1 Steel - Rt side	Fire Extinguisher:	No
Vertical Exhaust Stack:	No	Warning Triangle Kit:	No
Cab Roof Marker Lights:	Yes	Tow Light System:	No
Tread Type Rear:	Mud & Snow	Dual Controls:	Yes
* Tire Size-Front:	245/70R19.5	Front/Rear Safety Chains:	Yes Rear Only
Tire Depth-Front:	11/32	Light Plug Ins:	Yes CR6
* Tire Size-Rear Axle:	245/70R19.5	Hook Up Lights:	Yes
Tire Depth-Rear Axle:	6/32	* Wheel Lift/Wheel Lift Arms:	Yes with L-Arms
Top Hat Kit:	No	Wheel Lift Style:	Basic L-Arm Style
Lug Nut Covers:	No	Live Air Hook Up/Where:	No
Sub-Frame Finish:	Painted	Gas Cans/holders/Where:	No
Dump Angle:	Normal	Trash Cans/holders/Where:	No
Dock Stabilizer:	No	Self Loading Dollies:	No
Side Rails:	Steel Fixed	Go-Jaks:	No
Rub-Rails:	No	Trailer Hitch:	Built-In
# of Winches:	1	Special Equipment Storage/Where:	No
Winch Brand:	Ramsey		
Winch Capacity:	8,000# Worm Type		
Winch Clutch Release:	Yes Mechanical		
Winch Work Lights:	No		
Cable Tensioner:	Yes	Inspector Name	Status
Cable Roller Guide:	Yes	Enter name here	Mark. Dave
		Engine Check	Status
			Comments

Owner: _____

Location: _____

Engine Check	Status	Comments
Ability to Start	Starts Normally	
Engine Blow-By Check	Has some Blow-By	
Engine Oil Leaks	Oil leak observed (see Comments)	
Engine Noise	Engine sounds are normal	
Engine Warning Lights	No Check Engine Lights are on	
Engine Water Leaks	No Water Leaks	
Performance	Performs Normally	
Engine Mounts	In Good Condition	
Other Engine Notes		
Engine Brake		
Batteries	Status	Comments
Condition of Cables	In Good Condition	
Condition of Batteries	Need Replacement	
Load Test	Pass	
Cooling System	Status	Comments
Radiator	In Good Condition	
Fan	In Good Condition	
Fan Clutch	In Good Condition	
Fan Shroud	In Good Condition	
Water Hoses	In Good Condition	
Fan Belt	Worn or Frayed	
Other Cooling Condition Notes		
Automatic Transmission Check	Status	Comments
Transmission Operation	Transmission Operates Normally	
Other Transmission Notes		
Manual Transmission Check	Status	Comments
Shifting	Shifts Normally	
Clutch Operation	Operates Normally	
Throw-Out Bearing	Operates Normally	
Transmission Noise		
Other Transmission Notes	Trans stuck in gear ...it out and getting fixed	
Overall Body Condition	Status	Comments
Overall Condition	Fair	
Other Overall Body Condition notes		
Cab Exterior	Status	Comments
Hood	Dented or Cracked	
Right Fender	Dented or Cracked	
Left Fender	Scratched	
Grille	In Good Condition	
Back of Cab	Good Condition	
Driver Side Door	Scratched	
Passenger Side Door	Good Condition	
Roof	Good Condition	
Other Cab Exterior Notes		
Fuel Tank Appearance	In Good Condition	

Cab Exterior	Status	Comments
Entry Steps	In Good Condition	
Head-Light Doors	Cracked/Broken or Missing	
Battery Box	In Good Condition	
Driver Side Door Hinges	In Good Condition	
Passenger Side Door Hinges	In Good Condition	
Front Bumper	Status	Comments
Factory Front Bumper	In Poor Condition	
Front Push Bumper		
Glass Condition	Status	Comments
Windshield	Good Condition	
Driver Side Window	Good Condition	
Passenger Side Window	Good Condition	
Back Window	Good Condition	
Other Glass Condition Notes		
Overall Interior Condition	Status	Comments
Overall Condition	Good	
Other Overall Interior Notes		
Interior Condition	Status	Comments
Drivers Seat	Needs Clean Up But Good Condition	
Passenger Seat	Good Condition	
Rear Seat		
Floor Mat		
Instrument Cluster	Excellent	
Dash	In Good Condition	
Door Panels	In Good Condition	-Driver door missing whole light and bezel. Passenger side missing lense
Electric Door Locks	Fair Condition	
Other Interior Condition Notes		
Electric Windows	Operate Properly	
Door Handles	In Good Condition	
Air Vents	In Good Condition	
Headliner	In Good Condition	
Other Interior Notes		
Door Seals	In Good Condition	
Floor Mats	Missing or In Need of Replacement	
Seat Belts	In Good Condition	
Windshield Wipers	Status	Comments
Wiper Arms	In Good Condition	
Wiper Blades	In Need of Repair	
Washer Tank	In Good Condition	
Washer Control Switch	In Good Condition	
Heating	Status	Comments
Heater Controls	In Good Condition	
Fan Motor	Excellent Condition	
Heater	Heats Appropriately	
Other Heat Notes		
Air Conditioning	Status	Comments

Owner: _____

Location: _____

Air Conditioning	Status	Comments
Overall Condition	In Good Operating Condition	
Air Conditioning Controls	In Good Condition	
Electrical System-Chassis	Status	Comments
Interior lights	All Interior Light Operate Missing both lower inter. Lights	
Turn Signals	Operate Normally	
Head Lights	Operate Normally	
Alternator	Performs Normally	
Guages	All Gauges Perform Properly	
Dash Lights	Dash Lights Perform Normally	
Cab Marker Lights	Marker Lights Perform Normally	
Back-Up Lights	Operate Normally	
Back-Up Alarm	Performs Normally	
4-Way Flashers	Performs Normally	
Windshield Wipers	Perform Normally. But washer don't work needs	
Other Electrical System Notes		
Cruise Control	Operates Normally	
Engine Throttle	Operates Normally (Note Type)	
Drive-Line	Status	Comments
U-Joints	In Good Condition	
Rear Differential	In good condition	
Transfer Case		
Other Drive-Line Notes		
Hanger Bearings	In Good Condition	
Brakes	Status	Comments
Air Compressor		
System Air Leaks		
Air Dryer		
Applied Brakes		
Brake Adjusters		
Air Lines		
Low Air Pressure Warning		
Front Brake Drums		
Front Drive Axle Brake Drums		
Front Brake Calipers	In Good Condition	
Front Brake Linings	50% or Better	
Pusher Axle Brake Drums		
Pusher Axle Brake Linings		
Front Drive Axle Brake Linings		
Rear Drive Axle Brake Drums		
Rear Brake Calipers	In Good Condition	
Rear Drive Axle Brake Linings	Under 50%	
Emergency Brake	Performs Normally	
ABS Light	Showing Normal (Not on)	

Brakes	Status	Comments
Brake Pedal Pads	Worn	
Other Brake Notes		
Shock Absorbers	Status	Comments
Front Shocks	Needs Replacement	
Rear Front Shocks		
Wheels	Status	Comments
Front Axle Rims/Wheels	Wheel In Good Condition	
Pusher Axle Rims/Wheels		
Front Drive Axle Rims/Wheels	Wheel In Good Condition	
Front Drive Axle Nuts and Studs (2) (2)	In Good Condition	
Rear Drive Axle Rims/Wheels	Wheel In Good Condition	
Fronts Axle Nut and Studs	In Good Condition	
Pusher Axle Nut and Studs		
Rear Drive Axle Nuts and Studs	In Good Condition	
Wheel Simulators Front Axle	Damaged	
Wheel Simulators Pusher Axle	In Good Condition	
Wheel Simulators Front Drive Axle	Damaged	
Wheel Simulators Rear Drive Axle	In Fair Condition	
Aluminum Wheels Front Axle		
Aluminum Wheels Pusher Axle		
Aluminum Wheels Front Drive Axle		
Aluminum Wheels Rear Drive Axle		
Wheel Hubs	Status	Comments
Front Wheel Seals	In Good Condition	
Pusher Axle Wheel Seals		
Front Drive Axle Wheel Seals		
Rear Drive Axle Wheel Seals	In Good Condition	
Oil Filled Hubs Front Axle	Leaking	
Oil Filled Hubs Pusher Axle		
Oil Filled Hubs Front Drive Axle		
Oil Filled Hubs Rear Drive Axle		
Front Wheel Bearings		
Front Drive Axle Wheel Bearings	Checked In Good Condition	
Pusher Axle Wheel Bearings		
Rear Drive Axle Wheel Bearings	Checked In Good Condition	
Tires	Status	Comments
Front Axle	Replaced With New	
Pusher Axle		
Front Drive Axle		
Rear Drive Axle	Replaced With New	
Notes on Tires	Front tires cracked. Chunk of rubber missing	
Exhaust System	Status	Comments
Manifold	In Good Condition	
Exhaust Tubing	In Good Condition	
Muffler	In Good Condition	
DPF System		

Owner: _____

Location: _____

Exhaust System	Status	Comments
Emissions Warning Light	Showing Normal	
Exhaust Shield	In Good Condition	
Exhaust Stack		
Exhaust Mounting Bracket	In Good Condition	
Frame	Status	Comments
Integrity of Frame	In good Condition	
Suspension	Status	Comments
Air Bags		
Air Leaks		
Air Lines		
Spring Packs	In Good Condition	
Front Spring Hangars	In Good Condition	
Rear Spring Hangars	In Good Condition	
Radius Arms		
Rear Suspension Bushings		
Air Leveling Valve		
Steering and Front Axle	Status	Comments
Steering Pump	Operates Normally. But needs cap to be replace	
Steering Lines	In Good Operating Condition	
Steering Sector	In Good Operating Condition	
King Pins/Ball Joints	Need Replacing	
Steering Shaft	In Good Condition	
Pitman Arm	In Good Condition	
Drag Link	In Good Condition	
Tie Rod	In Good Condition	
Toe in Check		
4x4 Hubs		
Steering Wheel	Steering Wheel in Good Cosmetic Condition	
Steering Wheel Position		
Fuel System	Status	Comments
Fuel Gauge	Works Normally	
Fuel Tank	Leaking	
Fuel Fill	Fills Normally	
Fuel Lines	In Good Condition	
Fuel Filter	Not Replaced	
Glow Plugs or Exhaust Heater	Status	Comments
Glow Plug Operation		
Intake Manifold Heater	Cycle Normally	
Fluids	Status	Comments
Windshield Washer	Full	
Engine Oil	Full	
Radiator Anti-Freeze	Low	
Transmission Fluid	Full	
Transfer Case Oil		
Front Drive Axle		
Rear Drive Axle		
Battery Acid Levels	Full	
Hydraulic Oil	At Proper Level	
Brake Fluid	At Proper Level	

Fluids	Status	Comments
Power Steering Fluid	Low	
Winch 1 Oil	Drained and Filled with New	
Winch 2 Oil		
Winch 3 (Above Cab) Oil		
Filters	Status	Comments
Water Filter		
Engine Oil Filter	Original (Not replaced)	
Transmission Oil Filter		
Fuel Filter		
Carrier Hydraulic System	Not Changed	
Engine Air Filter	In Need of Replacement	
Chassis Lubrication Points	Status	Comments
King Pins/Ball Joints	Appears Dry	
Tie-Rods Ends	Appears Dry	
Steering Shaft Bearing	Appears Dry	
Drag Link	Appears Dry	
Clutch Linkage	Appears Dry	
Throw-Out Bearing	Freshly Greased	
Drive-Line U-Joints	Appears Dry	
S-Cam Shafts		
Slack Adjusters		
Spring Hangars		
Door Locks and Hinges	In Need of Lubrication	
Overall Car Carrier Condition	Status	Comments
Overall Condition	Good	
Carrier Deck	Status	Comments
Aluminum Deck Condition		
Steel Deck Condition	Is Wash-Boarded	
Aluminum Deck Side-rails		
Steel Deck Side-rails	Significant Scratches or Marks	
Steel Deck Side-rails Paint	Significant Scratches or Marks	
Aluminum Tail Section		
Rear Rollers		
Re-movable Side Rails Steel		
Re-movable Side Rails Aluminum		
Anti-Tilt Protection System		
Power Take-Off	Status	Comments
Operation	Operates Normally	
Oil Leaks	Has Oil Leak	
PTO Warning Light	In Good Operating Condition	
Shifting Mechanism	Shifting Cable In Good Operating Condition	
Air Leaks		
Hydraulic Pump	Status	Comments
Oil Leaks		
Operation		
Pump Pressure		
Pump Flow		
Control Valve	Status	Comments
Oil Leaks	Leaks From Valve Section	
Operation	Operates Normally	

Owner: _____

Location: _____

Control Valve	Status	Comments
Control Levers and Rods	In Good Condition	
Control Box	In Excellent Condition	
Knobs	In Excellent Condition	
Control Decals	In Good Condition	
Hydraulic System Hoses	Status	Comments
Oil Leaks		
Hydraulic System Leaks	Status	Comments
Winch Hoses	No Oil Leaks	
Lift Cylinder Hoses	No Oil Leaks	
Extension Cylinder Hoses	No Oil Leaks	
Wheel-Lift Tilt Cylinder Hoses	No Oil Leaks	
Wheel-Lift Extend Cylinder Hoses (2)	No Oil Leaks	
Hydraulic Pump Hoses	No Oil Leaks	
Hydraulic Filter	Leaks from Filter	
Bed Lift Cylinders	No Oil Leaks	
Extend Cylinder	No Oil Leaks	
Wheel-Lift Tilt Cylinder	No Oil Leaks	
Wheel-Lift Extend Cylinder	No Oil Leaks	
Wheel-Lift Claw Cylinder Drivers Side		
Wheel-Lift Claw Cylinder Passenger Side		
Pylon	Status	Comments
Overall Condition	In Good Condition with Minor Scratches/Dents	
Winch	Status	Comments
Oil Leaks	No Oil Leaks	
Free-Wheel Mechanism Winch 1	Operates Normally	
Free-Wheel Mechanism Winch 2		
Free-Wheel Mechanism Winch 3		
Housing Winch 1		
Housing Winch 2	In Good Condition	
Housing Winch 3		
Operation Without Load		
Operation Without Load Notes		
Test Operation Loaded		
Test Operation Notes		
Winch 1 Cable	Replaced With New	
Winch 2 Cable		
Winch 3 Cable		
Cable Tensioner	In Good Condition	
Wheel-Lift	Status	Comments
L-Arms/Scoops	In Good Condition	
L-Arm Straps	Missing	
L-Arm Storage	In Good Condition	
Driver Side Claw		
Passenger Side Claw		
Driver Side Slide Tray	In Good Condition	
Passenger Side Slide Tray	Bent	
Passenger Side Slide Tray Locks	Replaced With New (See Comments)	
Driver Side Slide Tray Locks (2)	Replaced With New (See Comments)	

Wheel-Lift	Status	Comments
Driver Side Front Stops (Vulcan)		
Passenger Side Front Stops (Vulcan)		
Driver Side L-Arm Swivel		
Passenger Side L-Arm Swivel (2)		
Center Pivot Pin and Bushing	Worn and in Need of Replacement	
Wheel-Lift Cross-Bar	Worn at Pivot Point Needs Repair	
Pins and Bushings		
Extension Tube		
Outer Wheel-Lift Assembly		
Wheel-Lift Swivel Lock Pins		
Wheel-Lift Swivel Lock Pins (2)		
Scoop Locking Pins and Chains	In Good Condition	
Driver Side Claw Cylinders		
Wear Pads		
Carrier Electrical Systems	Status	Comments
Switch Panel	In Good Condition	
Overall Wiring Condition	In Good Condition	
Bed Wiring Harness Condition	In Good Condition	
Junction Boxes Condition	In Good Condition	
Marker Lights	In Good Condition	
Driver Side Turn Signals Upper	In Good Condition	
Passenger Side Turn Signals Upper	In Good Condition	
Driver Side Turn Signals Upper Lower	In Good Condition	
Passenger Side Turn Signals Lower	In Good Condition	
Extra Warning Lights		
Extra Clearance Lights		
Upper Work Lights	In Good Condition	
Lower Work Lights	In Good Condition	
Work Lights Mounted Near Winch		
Beacon Light	In Good Condition	
Tow Light Plug at Tail-Board		
License Plate Light	In Good Condition	
Tool Boxes	Status	Comments
Box Driver Side 1	In Good Condition	
Box Driver Side 2		
Box Passenger Side 1	In Good Condition	
Box Passenger Side 2		
Fenders	Status	Comments
Drivers Side	In Fair Condition	
Passenger Side	In Fair Condition	
Carrier Components	Status	Comments
Bed Hold-Downs	In Good Condition	
Rear Bed Mounting (Pivot Pin)	In Good Condition	
Driver Side Tail-Light Housing	In Good Condition	
Passenger Side Tail-Light Housing (2)	In Good Condition	
Rear Tail Section	In Good Condition	

Owner: _____

Location: _____

Body Lubrication Points	Status	Comments
Bed Pivot Pin	Appears to Have Been Regularly Serviced	
Lift Cylinder Pins	Freshly Greased	
Wheel-lift Tilt Pin	Appears Dry	
Wheel-Lift Pivot Pin	Appears Dry	
Wheel-Lift Upper Slide Pads	Appears Dry	
Wheel-Lif tLower Slide Pads	Appears Dry	
Deck Slide Back Wear Pads	Appears Dry	
Tool Box Door Hinges and Locks	In Need of Lube	
Carrier Chains	Status	Comments
Front Safety Chains		
Rear Safety Chains	In Good Condition	
V-Chains Chains	In Excellent Condition	
V-Chains Straps		
Mud-Flaps	Status	Comments
Mounting Brackets	In Good Condition	
Mud-Flap	In Good Condition	