



# Zip's Truck Equipment

316 W. Milwaukee Street  
New Hampton, Iowa 50659  
Phone: 641-394-3166  
Fax: 641-394-4044



## FIELD iD

### Visual Inspection

Page: 1 of 7

**Customer:** \_\_\_\_\_  
**Address:** \_\_\_\_\_  
**Serial No:** J12302  
**Equipment Type:** Light-Duty Tow Truck  
**Event Performed:** Light Duty Wrecker Inspection  
**Result:** Pass  
**Inspected By:** \_\_\_\_\_

**Division:** null  
**Location:** New Hampton, IA  
**Phone:** \_\_\_\_\_  
**Reference #:** 1GBJK39G87E142260  
**Order #:** \_\_\_\_\_  
**Inspected On:** 08/16/16 9:28 AM CDT  
**Total Score:** \_\_\_\_\_  
**Comments:** \_\_\_\_\_

Iowa Shop Service Tech 1

#### Light-Duty Tow Truck-J12302

\* Year: 2007  
\* Make: Chevrolet  
\* Model: 3500EC 4x4  
\* Drive Type: 4 Wheel Drive  
\* Engine Make: Vortec  
\* Engine Model: 8100  
\* Fuel Type: Gas  
\* Transmission Type: Automatic  
\* Odometer Reading: 211,925  
\* GVW: 12,000#  
\* GAWR Front: 4,800#  
\* GAWR Rear: 8,600#  
\* Rear Axle Ratio: 4.10  
\* Cab Trim Package: Silverado  
Rear Vision Camera System/Brand: Yes - Safety Vision  
Remote Keyless Entry: Yes  
\* Cab to Axle: 60"  
\* Wheel Base: 161"  
Wheel Type: Stainless Steel Wheel Simulators  
\* Cab Color ONLY: White/Blue  
\* Body Make: Chevron  
\* Body Model: 0408A  
\* Body Serial Number: 0408A-13315  
Body Width: 86"

\* Beacon/Lightbar Make: Tomar  
\* Beacon/Lightbar Model: Low Profile Flip Up  
PTO Type: Hot Shift  
Switch Panel & # Of Switches: Switch Panel - 12 TouchTek VI  
Remote Controls: Yes Corded In Cab 4 Button  
\* Wrecker Body/Pylon Color: White/Blue  
\* Brake Type: Hydraulic  
\* Suspension Type: Spring  
\* Air Conditioning: Yes  
\* Radio: No  
\* Driver Seat: Split Vinyl w/Head Rests & Center Console  
Rear Passenger Seat: Vinyl Bench Seat w/Head Rests  
Windows: Power  
Door Locks: Power with Remote  
Window Deflectors: Yes RH  
Cruise Control: Yes  
Tilt Steering Wheel: Yes  
Flooring: Rubber or Vinyl  
\* Bumper: Push Bumper  
Grille: Grille Guard  
Front Tow Hooks: Yes 2  
Extra Lights On CAB/Where: Yes - Under Cab & In Grille  
Jumper Cable Plug/Where: Yes

Owner: \_\_\_\_\_

Serial No: J12302

Location: New Hampton, IA

Cab Fenders:	Fiberglass Fenderettes
Mirrors:	Power Swing Out
Additional Mirrors:	Convex Mirrors
Cab Roof Marker Lights:	Yes
* Tire Size-Front:	LT215/85R16
Tire Depth-Front:	8/32"
* Tire Size-Rear:	LT215/85R16
Tire Depth-Rear:	6/32"
* Tow Slings:	Yes
# of Winches:	1
Winch Clutch Release:	Yes
Cable Tensioner:	Yes
Pylon:	Standard Steel
Work Lights:	Yes
Stop/Turn/Tail On Pylon:	Yes
Extra Lights on WRECKER/Where:	Yes - On Pylon & Body Sides
Toolbox System:	LH & RH
Dual Controls:	Yes
Rear Safety Chains:	Yes
Light Plug Ins:	Yes CR6
* Wheel Lift:	Yes
Wheel Lift Style:	Auto-Grip
Aluminum Rail Caps:	Yes
Straps/Rachets:	Yes
Other Equipment:	2 Shackles Mounted On Tailboard

Engine Check	Status	Comments
Ability to Start	Starts Normally	
Engine Blow-By Check	No Noticeable Blow-By Issue	
Engine Oil Leaks	Oil leak observed (see Comments)	-Small leak possible oil pan rear main Either rear main or possibly front trans seal
Engine Noise	Engine sounds are normal	-Belt squeak, goes away after a little bit, possibly alternator due to hard start Lubed pulleys, now squeak is gone Replaced PTO clutch
Engine Warning Lights	No Check Engine Lights are on	-Check engine light on Had multiple misfires change plugs and wires. Also changed 2 coil packs
Engine Water Leaks	No Water Leaks	
Performance	Performs Normally	
Engine Mounts	In Good Condition	
Other Engine Notes		
Engine Brake		
<b>Batteries</b>	<b>Status</b>	<b>Comments</b>
Condition of Cables	In Good Condition	-Has been cleaned

Batteries	Status	Comments
Condition of Batteries	In Good Condition	-Replaced battery
Load Testing	Pass	-Battery replaced with new test is for old battery
<b>Cooling System</b>	<b>Status</b>	<b>Comments</b>
Radiator	In Good Condition	
Fan	In Good Condition	
Fan Clutch	In Good Condition	
Fan Shroud	In Good Condition	
Water Hoses	In Good Condition	
Fan Belt	In Good Condition	
Other Cooling Condition Notes		
<b>Automatic Transmission Check</b>	<b>Status</b>	<b>Comments</b>
Transmission Operation	Transmission Operates Normally	
Other Transmission Notes		
<b>Manual Transmission Check</b>	<b>Status</b>	<b>Comments</b>
Shifting		
Clutch Operation		
Throw-Out Bearing		
Transmission Noise		
Other Transmission Notes		
<b>Overall Body Condition</b>	<b>Status</b>	<b>Comments</b>
Overall Condition	Fair	
Other Overall Body Condition notes	Passenger side front looks to have been hit. Minor scratches and paint chips .	-Straightened front corner out as best I could
<b>Cab Exterior</b>	<b>Status</b>	<b>Comments</b>
Hood	Good Condition	-Hail marks, minor rusting, passenger front corner bent Straightened front corner
Right Fender	Dented or Cracked	-Dented from push bumper hitting it Straightened out as best I could
Left Fender	Good Condition	-Rubs on driver door Replaced door hinges and it no longer rubs
Grille	In Good Condition	-Replaced with a good used one
Back of Cab	Scratched	-Small dents
Driver Side Door	Good Condition	-Paint where rubbing fender missing. Small dents. Replaced hinges on door and it no longer rubs fender
Passenger Side Door	Good Condition	
Roof	Good Condition	-Hail dents
Other Cab Exterior Notes		
Fuel Tank Appearance	In Good Condition	
Entry Steps	In Good Condition	-Right side dented. Left side plastic pads loose
Head-Light Doors		
Battery Box	In Good Condition	

Owner: \_\_\_\_\_

Location: New Hampton, IA

Cab Exterior	Status	Comments	Heating	Status	Comments
Driver Side Door Hinges	In Good Condition	-Needs to be replaced Replaced with new ones	Heater	Heats Appropriately	
Passenger Side Door Hinges	In Good Condition		Other Heat Notes		
Glass Condition	Status	Comments	Air Conditioning	Status	Comments
Windshield	Good Condition		Overall Condition	In Good Operating Condition	
Driver Side Window	Good Condition	-Slight tint	Air Conditioning Controls	In Good Condition	
Passenger Side Window	Good Condition	-Slight tint	Electrical System-Chassis	Status	Comments
Back Window	Good Condition		Interior lights	All Interior Light Operate	
Other Glass Condition Notes	Driver side spot mirror cracked, passenger side power mirror doesn't work	-Mirror cracked, pass side mirror doesn't work Replaced broken spot mirror Replaced door harness	Turn Signals	Operate Normally	
Overall Interior Condition	Status	Comments	Head Lights	Operate Normally	
Overall Condition	Good		Alternator	Performs Normally	
Other Overall Interior Notes			Gauges	All Gauges Perform Properly	
Interior Condition	Status	Comments	Dash Lights	Dash Lights Inoperative (see Comments)	-Trans temp, engine temp, battery voltage Gages back lights out
Drivers Seat	Good Condition	-Repairs were made to seat	Cab Marker Lights	Marker Lights Perform Normally	
Passenger Seat	Good Condition		Back-Up Lights	Operate Normally	-Repair, runs through flood lights
Rear Seat	Good Condition		Back-Up Alarm	Performs Normally	-Never installed Reinstalled new back up alarm
Floor Mat	Good Condition		4-Way Flashers	Performs Normally	
Instrument Cluster	Good	-Missing back lights for trans temp, battery voltage, and engine temp	Windshield Wipers	Perform Normally	
Dash	In Good Condition	-Front trim of dash not seated because of aftermarket switch panel and backup camera bracket Also missing piece by air bag switch	Other Electrical System Notes		
Door Panels	Cracked or Loose	-Not seated in between door frame and panel Fixed door panels	Cruise Control		
Electric Door Locks	Inoperative	-Driver side works passenger side inop-Repaired Replaced door harness	Engine Throttle		
Electric Windows	Inoperative	-Repaired, multiple faults in electrical system Replaced door harness	Drive-Line	Status	Comments
Other Interior Condition Notes	Headliner peeling	-Headliner coming down in spots Reglued headliner	U-Joints	In Good Condition	
Air Vents	In Good Condition	-Top fin on driver side vent missing	Rear Differential	In good condition	
Door Handles	In Good Condition	-Driver side outside door handle loose, glued into place Replaced handle	Transfer Case	Shifts and Engages Normally	
Other Interior Notes			Other Drive-Line Notes		
Windshield Wipers	Status	Comments	Hangar Bearings	In Good Condition	
Wiper Arms	In Good Condition		Brakes	Status	Comments
Wiper Blades	In Good Condition	-Replace- Replaced with new	Air Compressor		
Washer Tank	In Good Condition		System Air Leaks		
Washer Control Switch	In Good Condition		Applied Brakes		
Heating	Status	Comments	Brake Adjusters		
Heater Controls	In Good Condition		Air Lines		
Fan Motor	Excellent Condition	-Squeaked a little when first turned on, but hasn't since	Low Air Pressure Warning		
			Front Brake Drums	In Good Condition - from On Truck Inspection	
			Pusher Axle Brake Drums		
			Front Brake Calipers	In Good Condition	
			Front Drive Axle Brake Drums		
			Front Brake Linings	60 or Better	
			Rear Drive Axle Brake Drums	In Good Condition - on truck visual	
			Rear Brake Calipers	In Good Condition	
			Pusher Axle Brake Linings		
			Front Drive Axle Brake Linings		
			Rear Drive Axle Brake Linings	60 or Better	

Owner: \_\_\_\_\_

Location: New Hampton, IA

Brakes	Status	Comments
Emergency Brake	Doesn't Hold Properly - Needs Repair	-Cable broken
ABS Light	Showing Normal (Not on)	
Brake Pedal Pads	In Good Condition	
Other Brake Notes		-Hydraulic booster leaking Replaced with used booster
Air Dryer		
Wheels	Status	Comments
Front Axle Rims/Wheels	Wheel In Good Condition	
Pusher Axle Rims/Wheels		
Front Drive Axle Rims/Wheels		
Rear Drive Axle Rims/Wheels	Wheel In Good Condition	
Fronts Axle Nut and Studs	In Good Condition	
Pusher Axle Nut and Studs		
Front Drive Axle Nuts and Studs (2) (2)		
Rear Drive Axle Nuts and Studs	In Good Condition	
Wheel Simulators Front Axle	In Good Condition	-Driver side missing cap
Wheel Simulators Pusher Axle		
Wheel Simulators Front Drive Axle		
Wheel Simulators Rear Drive Axle	In Good Condition	
Aluminum Wheels Front Axle		
Aluminum Wheels Pusher Axle		
Aluminum Wheels Front Drive Axle		
Aluminum Wheels Rear Drive Axle		
Wheel Hubs	Status	Comments
Front Wheel Seals		
Front Drive Axle Wheel Bearings	Not Adjusted but No Issue Visible	
Front Wheel Bearings		
Pusher Axle Wheel Seals		
Front Drive Axle Wheel Seals	In Good Condition	
Oil Filled Hubs Front Drive Axle		
Rear Drive Axle Wheel Seals	In Good Condition	
Oil Filled Hubs Front Axle		
Pusher Axle Wheel Bearings		
Oil Filled Hubs Pusher Axle		
Oil Filled Hubs Rear Drive Axle	In Good Condition	
Rear Drive Axle Wheel Bearings	Not Adjusted but No Issue Visible	
Tires	Status	Comments
Front Axle		
Pusher Axle		
Front Drive Axle	In Good Condition 60% or Better	
Rear Drive Axle	In Good Condition 60% or Better	
Notes on Tires		
Exhaust System	Status	Comments
Manifold	In Good Condition	
Exhaust Tubing	In Good Condition	

Exhaust System	Status	Comments
Muffler	In Good Condition	
DPF System		
Emnsions Warning Light		
Exhaust Shield	In Good Condition	
Exhaust Stack		
Exhaust Mounting Bracket	In Good Condition	
Frame	Status	Comments
Integrity of Frame	In good Condition	-Surface rust
Suspension	Status	Comments
Air Bags		
Air Leaks		
Air Lines		
Spring Packs	In Good Condition	
Front Spring Hangars		
Rear Spring Hangars	Need to be Replaced (See Comments)	-Broken spring leaf on pass. side.
Radius Arms	In Good Condition	
Rear Suspension Bushings	In Good Condition	
Air Leveling Valve		
Steering and Front Axle	Status	Comments
Steering Pump	Operates Normally	
Steering Lines	In Good Operating Condition	-Fixed with seal kit, no leak visible now -Lines leaking leaving puddles on floor
Steering Sector	In Good Operating Condition	
King Pins/Ball Joints	In Good Condition	-Replaced
Steering Shaft	In Good Condition	
Pitman Arm	In Good Condition	-Learned was bad, replaced along with idle arm
Drag Link	In Good Condition	
Tie Rod	In Good Condition	
Toe in Check	In Tolerance	-Due to problems in front end, toe will be accused after repairs Reset toe
4x4 Hubs	Operate Normally	-Control arm bushings on driver side are bad Outer rubber starting to chunk out but inner bushing and rubber still good
Steering Wheel	Wheel has Cosmetic Issues	
Steering Wheel Position	Wheel is Centered When Driven	
Fuel System	Status	Comments
Fuel Gauge	Works Normally	
Fuel Tank	In Good Condition	
Fuel Fill	Fills Normally	
Fuel Lines	In Good Condition	
Fuel Filter	Not Replaced	
Glow Plugs or Exhaust Heater	Status	Comments
Glow Plug Operation		
Intake Manifold Heater		
Fluids	Status	Comments
Windshield Washer	Full	

Owner: \_\_\_\_\_

Location: New Hampton, IA

Fluids	Status	Comments
Engine Oil	Full	-Replaced missing oil dipstick Changed oil at 211,929 mi.
Radiator Anti-Freeze	Full	
Transmission Fluid	Full	
Transfer Case Oil	Full	
Front Drive Axle	Full	-Leaks  Fixed leak and refilled
Rear Drive Axle	Full	
Battery Acid Levels	Not Checked	
Hydraulic Oil	At Proper Level	-Screen full of rust, needs to be pulled out and cleaned  Cleaned screen and topped off
Brake Fluid	At Proper Level	
Power Steering Fluid	At Proper Level	-Leak  Cleaned off everything and didn't find a new leak
Winch 1 Oil	Not Checked	-Warn winch, sealed unit
Winch 2 Oil		
Winch 3 (Above Cab) Oil		
Filters	Status	Comments
Water Filter		
Engine Oil Filter	Replaced	
Transmission Oil Filter	Replaced	
Fuel Filter	Original (Not replaced)	
Carrier Hydraulic System	Removed and Replaced	-Needs replacement-Replaced
Overall Wrecker Body Condition	Status	Comments
Overall Condition	Good	
Wrecker Body Condition	Status	Comments
Body Sides Condition	Has Minor Scratches and Wear Marks	
Body Deck Condition	Has Minor Scratches Wear Marks	
Front of Body Condition	Minor Scratches or Rock Chips	
Body Side Condition	Has Minor Scratches Wear Marks	
Side Rail Cap Condition (2)	In Good Condition	
Driver Side Tool Box 1 Condition	In Fair Condition	-Latch missing springs, missing one chain, lock frozen-repaired
Passenger Side Tool Box 1 Condition	In Fair Condition	-Can't open and lock frozen- repaired
Tunnel Tool Box 1 Condition		
Tail-Board Condition	Rusty - Minor Spots	
Power Take-Off	Status	Comments
Operation	Operates Normally	
Oil Leaks	No Oil Leaks	
PTO Warning Light	In Good Operating Condition	
Shifting Mechanism	Electrical Switch Working Properly	
Air Leaks		
Hydraulic Pump	Status	Comments
Oil Leaks	No Oil Leaks	
Operation	Pump Operates Normally	

Hydraulic Pump	Status	Comments
Pump Pressure	Tested to 2200#	
Pump Flow	Not Tested	
Controls & Valve	Status	Comments
Oil Leaks	No Oil Leaks	
Operation	Operates Normally	-Unsure if the controls are to rusty or if it is in the valve block, controls were rusty, worked with lube back in forth and they are now freed up  Also cleaned out cap on power tilt, doesn't stick anymore
Control Levers and Rods	In Good Condition	-Worked out with lube
Knobs	In Good Condition	-Missing one lever and one knob, for wheel lift tilt-Replaced  Also replaced bad decals
Hydraulic System Hoses	Status	Comments
Oil Leaks	In Operating Condition	
Hydraulic System Leaks	Status	Comments
Winch Hoses	No Oil Leaks	
Boom Lift Cylinder Hoses	No Oil Leaks	
Boom Extension Cylinder Hoses	No Oil Leaks	
Wheel-Lift Tilt Cylinder Hoses	No Oil Leaks	
Wheel-Lift Extend Cylinder Hoses (2)	No Oil Leaks	
Wheel-Lift Up/Down Cylinder Hoses (2)	No Oil Leaks	
Hydraulic Pump Hoses	No Oil Leaks	
Hydraulic Filter	No Oil Leaks	
Bed Lift Cylinders		
Extend Cylinder	No Oil Leaks	
Wheel-Lift Tilt Cylinder	No Oil Leaks	
Wheel-Lift Extend Cylinder	No Oil Leaks	
Wheel-Lift Claw Cylinder Drivers Side	Operates Normally No Oil Leaks	
Wheel-Lift Claw Cylinder Passenger Side	Operates Normally No Oil Leaks	
Cylinder Condition	Status	Comments
Boom Lift Cylinder	Operates Normally	
Boom Extend Cylinder	Operates Normally	
Wheel-Lift Extend Cylinder	Operates Normally	
Wheel-Lift Tilt Cylinder	Operates Normally	
Wheel-Lift Lift Cylinder	Operates Normally	
Wheel-Lift Lift Claw Cylinders	Operates Normally	
Pylon	Status	Comments
Overall Condition	In Good Condition with Minor Scratches/Dents	-Beacon flip brackets are bent- straightened when new beacon was installed
Winch	Status	Comments
Oil Leaks	No Oil Leaks	
Free-Wheel Mechanism Winch 1	Operates Normally	
Free-Wheel Mechanism Winch 2		
Free-Wheel Mechanism Winch 3		
Housing Winch 1	In Good Condition	
Housing Winch 2		
Housing Winch 3		
Operation Without Load	Performs Normally	

Owner: \_\_\_\_\_

Location: New Hampton, IA

Winch	Status	Comments
Operation Without Load Notes		
Test Operation Loaded		
Test Operation Notes		
Winch 1 Cable	In Good Condition	
Winch 2 Cable		
Winch 3 Cable		
Wheel-Lift	Status	Comments
L-Arms/Scoops		
L-Arm Straps	In Fair Condition	
L-Arm Storage		
Driver Side Claw	In Fair Condition	-Starting to wear in claw Replaced pin and rewelded end back up
Passenger Side Claw	In Fair Condition	-Bushing worn, learned that claw was worn excessively would need new claw Replaced pin and welded end back up
Driver Side Slide Tray		
Passenger Side Slide Tray		
Passenger Side Slide Tray Locks		
Driver Side Slide Tray Locks		
Driver Side Front Stops (Vulcan)	In Good Condition	
Passenger Side Front Stops (Vulcan)	In Good Condition	
Driver Side L-Arm Swivel		
Passenger Side L-Arm Swivel		
Center Pivot Pin and Bushing	In Good Condition	-Learned that t bar is worn out, would need all new t bar to tighten up Replaced worn out pivot pin and it took out a lot of the play
Wheel-Lift Cross-Bar	In Good Condition	-Center pivot worn excessive, would need replacement Replaced pivot pin
Pins and Bushings	In Good Condition	
Extension Tube	In Good Condition	
Outer Wheel-Lift Assembly	In Good Condition	
Wheel-Lift Swivel Lock Pins		
Wheel-Lift Swive Removeable Lock Pins		
Scoop Locking Pins and Chains		
Driver Side Claw Cylinders	In Good Condition	
Main Pivot Pin for Tilting	In Good Condition	
Wrecker Electrical Systems	Status	Comments
Switch Panel	In Good Condition	-One panel is not secured and has some electrical issues Fixed switch panel issues
Overall Wiring Condition	In Good Condition	
Bed Wiring Harness Condition	In Good Condition	
Junction Boxes Condition	In Good Condition	
Marker Lights	In Good Condition	-All marker lights fixed
Driver Side Turn Signals Upper	In Good Condition	
Passenger Side Turn Signals Upper	In Good Condition	
Driver Side Turn Signals Upper Lower	In Good Condition	

Wrecker Electrical Systems	Status	Comments
Passenger Side Turn Signals Lower	In Good Condition	
Extra Warning Lights	In Good Condition	-Driver side body side strobe, driver side tailboard strobe, passenger side upper strobe, and all four in grill- are all Inop or dim Replaced bad strobe lights
Extra Clearance Lights	In Good Condition	-All skirt lighting and lights going up pylon are Inop- all repaired
UpperWork Lights	In Good Condition	-Repaired
Lower Work Lights	In Good Condition	-Lights unattached-repaired with new lights
Work Lights Mounted Near Winch		
Beacon Light 2		
Beacon Light 3		
Beacon Light 1	In Good Condition	-Most of beacon lights are inop- new beacon installed
Tow Light Plug at Tail-Board	In Good Condition	-Green in plug and no light bar but has receiver, replaced plug with new and has new tow light kit
Tool Boxes	Status	Comments
Box Driver Side 1	In Good Condition	-One cable broken lock frozen- cable and lock repaired Replaced latch
Box Driver Side 2		
Box Passenger Side 1	In Fair Condition	-Rubber missing also missing latch and lock frozen- lock and cables for door repaired
Box Passenger Side 2		
Fenderettes	Status	Comments
Drivers Side		
Passenger Side		
Wrecker Lubrication	Status	Comments
Lift Cylinder Pins		
Tilt Cylinder Pins		
Wheel-lift Tilt Pin	Appears to Have Been Regularly Serviced	
Wheel-Lift Cross-Bar Pivot Pin	Appears to Have Been Regularly Serviced	
Upper Wheel-Lift Extension Slide Pads	Appears Dry	
Lower Wheel-Lift Extension Slide Pads (2)	Appears Dry	-Replaced wear pad with new ones
Wheel-Lift Lift Tower Wear Pads	Appears Dry	
Wheel-Lift Arm Pins and Bushings	Appears to Have Been Regularly Serviced	
Tool Box Hinges and Latches	Lubricated	
Chains	Status	Comments
Rear Safety Chains	In Excellent Condition	-Chains are tangled together but look to be ok, needs safety clips, chains are free and have new safety clips
J-Hook Chains	In Excellent Condition	-Missing Replaced with new ones
Tow Sling	Status	Comments
Sling Arms	In Good Operating Condition	-Freed up
Sling Belts	In Good Operating Condition	
Top Lift Bar	In Good Condition	

Owner: \_\_\_\_\_

Location: New Hampton, IA

<b>Tow Sling</b>	<b>Status</b>	<b>Comments</b>
Lower Lift Bar	In Good Condition	
<b>Chassis Lubrication</b>	<b>Status</b>	<b>Comments</b>
King Pins/Ball Joints	Appears Dry	
Tie-Rod Ends	Appears Dry	
Drag Link	Appears Dry	
Steering Shaft	Appears to Have Been Regularly Serviced	
Drive-Line U-Joints	Appears to Have Been Regularly Serviced	
Spring Shackles		
Door Locks and Hinges	Lubricated	
<b>Wrecker Mounting System</b>	<b>Status</b>	<b>Comments</b>
Front Bed Mounting Brackets	Brackets and Bolts in Good Condition	
Rear Bed Mounting Brackets (2)	Brackets and Bolts in Good Condition	
<b>Shock Absorbers</b>	<b>Status</b>	<b>Comments</b>
Front Shocks	In Good Condition	-Replaced with new ones
Rear Shocks	In Good Condition	